

27-Oct-03

**Street Construction, Reconstruction and Resurfacing Treatment History 1999 - 2002 (10/17/03 Edited 2002 Street Inventory)**

Text Partial blocks  
 Text 2003 Jobs  
 Text 2003 Partial blocks

Street Inventory ID #	Street	Block	2002 Council District #	1990 Census Tract #	Street Inventory Block				Applicable Inventory Improvement Year			Project Group Name	Treatment	Funding	Program	Work Plan Year
					Length	Width	Ln Mi	Type Surface	Construction	Resurfacing	Work					
8	Aberdeen Av.	6200	13	76.04	530	26	0.26	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
9	Aberdeen Av.	6300	13	76.04	510	26	0.25	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
10	Aberdeen Av.	6400	13	76.04	1,007	26	0.50	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
36718	Al Patterson Dr.	7000	8	112.00	212	32	0.13	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
271	Alabama Av.	2300	6	56.00	408	26	0.20	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
271	Alabama Av.	2300	6	56.00	408	26	0.20	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
272	Alabama Av.	2400	6	56.00	435	26	0.21	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
272	Alabama Av.	2400	6	56.00	435	26	0.21	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
273	Alabama Av.	2500	6	56.00	402	26	0.20	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
273	Alabama Av.	2500	6	56.00	402	26	0.20	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
274	Alabama Av.	2600	6	56.00	632	26	0.31	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
274	Alabama Av.	2600	6	56.00	632	26	0.31	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
319	Alaska Av.	2800	6	56.00	622	26	0.31	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
376	Alderson St.	3500	14	2.01	310	26	0.15	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
377	Alderson St.	3600	14	2.01	345	26	0.17	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
378	Alderson St.	3700	14	2.01	372	30	0.21	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
36802	All Star Way	1400	2	19.00	419	46	0.37	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
454	Allen St.	1000	14	16.00	264	24	0.12	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
454	Allen St.	1000	14	16.00	264	24	0.12	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
455	Allen St.	2000	14	17.02	280	30	0.16	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
455	Allen St.	2000	14	17.02	280	30	0.16	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
534	Alps Dr.	9300	8	118.00	305	26	0.15	Asphalt	1963	2002	2002	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
544	Alta Mesa Dr.	2900	8	167.01	410	24	0.19	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
545	Alta Mesa Dr.	3000	8	167.01	520	24	0.24	Asphalt	1971	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
546	Alta Mesa Dr.	3100	8	167.01	450	26	0.22	Asphalt	1971	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
575	Alto Caro Dr.	7200	12	136.05	997	26	0.49	Asphalt	1969	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
33741	Amador Av.	18500	12	317.98	990	26	0.49	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
36719	Amber Dr.	7100	8	112.00	410	33	0.26	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36720	Amber Dr.	7200	8	112.00	344	32	0.21	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36721	Amber Dr.	7300	8	112.00	471	32	0.29	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
652	American Wy.	7100	8	109.00	460	36	0.31	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
32983	American Wy.	7200	8	109.00	355	36	0.24	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
654	Amesbury Dr.	4500	9	79.05	650	36	0.44	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
655	Amesbury Dr.	4600	9	79.05	1,223	36	0.83	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
656	Amesbury Dr.	4700	9	79.05	412	36	0.28	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
657	Amesbury Dr.	4800	9	79.05	412	36	0.28	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
692	Anaconda Dr.	9000	8	117.00	856	26	0.42	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
693	Anaconda Dr.	9100	8	117.00	294	26	0.14	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
760	Anita St.	5400	9	3.00	870	26	0.43	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
761	Anita St.	5500	9	3.00	485	26	0.24	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
762	Anita St.	5600	9	3.00	620	26	0.31	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
763	Anita St.	5700	14	2.02	624	26	0.31	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
764	Anita St.	5800	14	2.02	652	26	0.32	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
765	Anita St.	5900	14	2.02	450	26	0.22	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
767	Anita St.	6100	14	2.01	943	26	0.46	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
768	Anita St.	6200	14	2.01	967	26	0.48	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
775	Ann Arbor Av.	200	4	59.02	320	44	0.27	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
776	Ann Arbor Av.	300	4	59.02	435	44	0.36	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000

Street History Improvements 1999-2002

777	Ann Arbor Av.	400	4	59.02	400	44	0.33	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
778	Ann Arbor Av.	500	4	59.02	534	44	0.45	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
779	Ann Arbor Av.	600	4	59.02	215	44	0.18	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
780	Ann Arbor Av.	700	4	59.01	430	36	0.29	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
825	Annex Av.	1900	2	8.00	459	28	0.24	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
858	Antoinette St.	7500	5	93.04	462	26	0.23	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
859	Antoinette St.	7600	5	93.04	471	26	0.23	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
860	Antoinette St.	7700	5	93.04	471	30	0.27	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
878	Apache La.	800	8	118.00	955	26	0.47	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
879	Apache La.	900	8	118.00	173	26	0.09	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
882	Appian Wy.	100	6	54.00	500	22	0.21	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
883	Appian Wy.	200	6	54.00	200	22	0.08	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
884	Appian Wy.	300	6	54.00	970	26	0.48	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
885	Appian Wy.	400	6	54.00	331	26	0.16	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
31141	Arbor Downs Dr.	16200	12	136.19	300	26	0.15	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
31142	Arbor Downs Dr.	16300	12	136.19	310	26	0.15	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
31143	Arbor Downs Dr.	16400	12	136.19	334	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
942	Arbor Park Dr.	9200	10	78.10	660	26	0.33	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
943	Arbor Park Dr.	9300	10	78.10	336	26	0.17	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
944	Arbor Park Dr.	9400	10	78.10	554	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
31617	Arborside Dr.	9000	10	78.10	395	26	0.19	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
985	Arizona Av.	2100	6	54.00	479	26	0.24	Concrete	2000	2000	Construction	Construction	Construction	Construction	2000	
985	Arizona Av.	2100	6	54.00	479	26	0.24	Concrete	2000	2000	Construction	Construction	Construction	Construction	2000	
986	Arizona Av.	2200	6	54.00	118	26	0.06	Concrete	2000	2000	Construction	Construction	Construction	Construction	2000	
986	Arizona Av.	2200	6	54.00	118	26	0.06	Concrete	2000	2000	Construction	Construction	Construction	Construction	2000	
988	Arizona Av.	2400	6	56.00	450	26	0.22	Concrete	2001	2001	Construction	Construction	Construction	Construction	2001	
989	Arizona Av.	2500	6	56.00	401	26	0.20	Concrete	2001	2001	Construction	Construction	Construction	Construction	2001	
990	Arizona Av.	2600	6	56.00	650	26	0.32	Concrete	2001	2001	Construction	Construction	Construction	Construction	2001	
991	Arizona Av.	2700	6	56.00	665	26	0.33	Concrete	2001	2001	Construction	Construction	Construction	Construction	2001	
1045	Ash La.	3300	7	28.00	304	26	0.15	Concrete	1999	1999	Construction	Construction	Construction	Construction	1999	
1045	Ash La.	3300	7	28.00	304	26	0.15	Concrete	1999	1999	Construction	Construction	Construction	Construction	1999	
1046	Ash La.	3400	7	28.00	303	26	0.15	Concrete	1999	1999	Construction	Construction	Construction	Construction	1999	
1046	Ash La.	3400	7	28.00	303	26	0.15	Concrete	1999	1999	Construction	Construction	Construction	Construction	1999	
1274	Authon Dr.	7200	12	136.05	426	26	0.21	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
1275	Authon Dr.	7300	12	136.05	493	26	0.24	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
1276	Authon Dr.	7400	12	136.05	530	26	0.26	Asphalt	1972	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
36775	Avalon Creek Ct.	9900	13	76.03	208	36	0.14	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
1383	Bahama Dr.	2400	3	68.00	875	40	0.66	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
1384	Bahama Dr.	2500	3	68.00	990	40	0.75	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
1385	Bahama Dr.	2600	3	68.00	870	48	0.79	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
1432	Bandera Av.	6700	13	77.00	600	36	0.41	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
1433	Bandera Av.	6800	13	77.00	275	30	0.16	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
32225	Barfield Dr.	6400	12	317.98	580	26	0.29	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
32226	Barfield Dr.	6500	12	317.98	516	26	0.25	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
1597	Baronne Cir.	10100	9	129.00	1,223	26	0.60	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
1598	Baronne Cir.	10200	9	129.00	298	26	0.15	Concrete		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
1610	Barry Av.	4600	7	25.00	124	26	0.06	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
1611	Barry Av.	4700	7	25.00	446	26	0.22	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
1612	Barry Av.	4800	7	25.00	225	26	0.11	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
32992	Beacon St. (N)	300	14	13.02	365	36	0.25	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
32993	Beacon St. (N)	400	14	13.02	380	36	0.26	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
32994	Beacon St. (N)	500	14	13.02	365	26	0.18	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
32995	Beacon St. (N)	600	14	13.02	365	26	0.18	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
1680	Beacon St. (N)	700	14	14.00	380	26	0.19	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
1681	Beacon St. (N)	800	14	14.00	200	24	0.09	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
1682	Beacon St. (N)	900	14	14.00	276	26	0.14	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
1682	Beacon St. (N)	900	14	14.00	276	26	0.14	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
1683	Beacon St. (N)	1000	14	14.00	270	26	0.13	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999

Street History Improvements 1999-2002

1683	Beacon St. (N)	1000	14	14.00	270	26	0.13	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
1684	Beacon St. (N)	1100	14	14.00	400	26	0.20	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
1684	Beacon St. (N)	1100	14	14.00	400	26	0.20	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
35732	Beacon St. (N)	1200	14	11.01	310	26	0.15	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
32232	Beautycrest Ct.	300	8	117.00	150	26	0.07	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
1762	Beckley Av. (S)	700	1	48.00	485	30	0.28	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
1763	Beckley Av. (S)	800	1	48.00	296	30	0.17	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
1764	Beckley Av. (S)	900	1	48.00	360	30	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
1765	Beckley Av. (S)	1000	1	48.00	650	30	0.37	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
1892	Belleau Av.	1200	3	44.00	429	22	0.18	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
1967	Bending Oaks Trl.	1600	5	119.00	930	26	0.46	Asphalt	1971	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
2065	Berry Knoll Dr.	10500	11	131.02	455	26	0.22	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
32240	Berthoud Pass	6200	12	317.98	410	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
32239	Bessemer St.	100	6	100.00	666	22	0.28	Asphalt		2000	2000	2000 City Forces	Resurfacing	General Fund	City Forces	2000
2124	Bexar St.	4900	7	39.02	253	36	0.17	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
2125	Bexar St.	5000	7	39.02	636	36	0.43	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
2126	Bexar St.	5100	7	39.02	235	36	0.16	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
2127	Bexar St.	5200	7	39.02	275	36	0.19	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
2128	Bexar St.	5300	7	39.02	515	36	0.35	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
2129	Bexar St.	5400	7	39.02	219	36	0.15	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
2130	Bexar St.	5500	7	39.02	478	36	0.33	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
2131	Bexar St.	5600	7	39.02	377	36	0.26	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
2132	Bexar St.	5700	7	39.02	387	36	0.26	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
2186	Birch St.	8300	5	117.00	304	26	0.15	Asphalt	1955	2002	2002	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
2187	Birch St.	8400	5	117.00	546	26	0.27	Asphalt	1955	2002	2002	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
36806	Bishop Allen La.	2500	8	109.00	7,800	26	3.84	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
2232	Bishop Av. (N)	400	1	47.00	290	30	0.16	Asphalt		2001	2001	CDBG	Resurfacing	Other Project	CDBG	2001
2233	Bishop Av. (N)	500	1	47.00	155	40	0.12	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
2234	Bishop Av. (N)	600	1	42.00	444	59	0.50	Asphalt	1957	2001	2001	CDBG	Resurfacing	Other Project	CDBG	2001
2245	Bishop Av. (S)	500	1	50.00	340	30	0.19	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
2246	Bishop Av. (S)	600	1	50.00	338	30	0.19	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
2247	Bishop Av. (S)	700	1	50.00	277	30	0.16	Asphalt	1967	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
2288	Blackwood Dr.	7000	10	78.13	950	26	0.47	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
2373	Blue Meadow St.	1600	5	119.00	836	26	0.41	Asphalt	1971	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
2385	Bluefield Dr.	7100	12	136.05	185	26	0.09	Asphalt	1972	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
2386	Bluefield Dr.	7200	12	136.05	531	26	0.26	Asphalt	1972	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
2387	Bluefield Dr.	7300	12	136.05	385	26	0.19	Asphalt	1972	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
2388	Bluefield Dr.	7400	12	136.05	525	26	0.26	Asphalt	1973	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
2436	Bob O Link Dr.	6400	9	80.00	880	36	0.60	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
2437	Bob O Link Dr.	6500	9	80.00	970	36	0.66	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
2438	Bob O Link Dr.	6600	9	80.00	364	36	0.25	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
2480	Boedeker St.	7700	13	79.06	450	26	0.22	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
2481	Boedeker St.	7800	13	79.06	400	26	0.20	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
2482	Boedeker St.	7900	13	79.06	373	26	0.18	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
2483	Boedeker St.	8000	13	79.06	373	26	0.18	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
2484	Boedeker St.	8100	13	79.06	347	26	0.17	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
2485	Boedeker St.	8200	13	79.06	375	26	0.18	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
2486	Boedeker St.	8300	13	79.06	312	26	0.15	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
2519	Bolivar Dr.	3500	2	98.02	1,275	26	0.63	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
2520	Bolivar Dr.	3600	2	98.02	620	26	0.31	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
36664	Bowles La.	14100	8	170.02	410	30	0.23	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
2777	Bowling Green Av.	2600	4	88.01	587	26	0.29	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
2832	Bramlett Dr.	7100	5	93.01	570	26	0.28	Asphalt	1960	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
2833	Bramlett Dr.	7200	5	93.01	530	26	0.26	Asphalt	1960	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
2834	Bramlett Dr.	7300	5	93.01	565	26	0.28	Asphalt	1960	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
2840	Brandon St.	1600	1	51.00	391	26	0.19	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
2841	Brandon St.	1700	1	51.00	328	26	0.16	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
2844	Brandon St.	2000	3	53.00	400	30	0.23	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999

Street History Improvements 1999-2002

2845	Brandon St.	2100	3	53.00	406	30	0.23	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
2846	Brandon St.	2200	3	53.00	375	30	0.21	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
2872	Breckenridge Dr.	12500	11	132.00	150	36	0.10	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
2873	Breckenridge Dr.	12600	11	132.00	590	36	0.40	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
33791	Bremerton Dr.	7000	12	317.98	775	26	0.38	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
31194	Brentfield Dr.	6900	12	136.19	1,485	26	0.73	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
2909	Briar Cove Dr.	6600	11	136.08	596	26	0.29	Asphalt	1965	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
2910	Briar Cove Dr.	6700	11	136.08	525	26	0.26	Asphalt	1965	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
2911	Briar Cove Dr.	6800	11	136.08	525	26	0.26	Asphalt	1965	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
33810	Briar bend Rd.	4000	12	317.02	735	26	0.36	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
32648	Briar bend Rd.	4100	12	317.02	655	26	0.32	Asphalt	1981	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
32649	Briar bend Rd.	4200	12	317.02	535	26	0.26	Asphalt	1981	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
2928	Briarmeade Dr.	6500	11	136.08	1,224	26	0.60	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
2929	Briar meadow Dr.	7000	11	131.02	1,144	36	0.78	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
32242	Briarnoll Dr.	7200	12	317.98	587	26	0.29	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
2955	Bridges St.	400	5	117.00	553	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
3057	Brockbank Dr.	10700	6	97.01	1,031	36	0.70	Asphalt		1999	1999	Other Project	Resurfacing	Other Project	Other Project	1999
3171	Brooklyn Av. (W)	2400	1	53.00	714	26	0.35	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
3171	Brooklyn Av. (W)	2400	1	53.00	714	26	0.35	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
3172	Brooklyn Av. (W)	2500	1	53.00	635	26	0.31	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
3172	Brooklyn Av. (W)	2500	1	53.00	635	26	0.31	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
3173	Brooklyn Av. (W)	2600	1	53.00	675	26	0.33	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
3173	Brooklyn Av. (W)	2600	1	53.00	675	26	0.33	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
3174	Brooklyn Av. (W)	2700	1	53.00	790	26	0.39	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
3174	Brooklyn Av. (W)	2700	1	53.00	790	26	0.39	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
3175	Brooklyn Av. (W)	2800	1	53.00	845	26	0.42	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
3175	Brooklyn Av. (W)	2800	1	53.00	845	26	0.42	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
33449	Brookside Dr. (N)	400	14	13.01	500	26	0.25	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
33450	Brookside Dr. (N)	500	14	13.01	375	26	0.18	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
33451	Brookside Dr. (N)	600	14	13.01	375	26	0.18	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
3232	Brookwood Dr.	700	4	60.02	300	26	0.15	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
3233	Brookwood Dr.	800	4	60.02	610	26	0.30	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
3234	Brookwood Dr.	900	4	60.02	630	26	0.31	Asphalt	1955	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
3235	Brookwood Dr.	1000	4	60.02	180	26	0.09	Asphalt	1955	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
3241	Browder St.	300	2	31.01	220	22	0.09	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
36693	Bryce Canyon Rd.	5100	3	107.02	1,036	36	0.71	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36694	Bryce Canyon Rd.	5200	3	107.02	861	36	0.59	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
3520	Burninglog La.	12500	11	190.16	547	36	0.37	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
3521	Burninglog La.	12600	11	190.16	280	36	0.19	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
3522	Burninglog La.	12700	11	190.16	360	36	0.25	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
3601	Burnside Av.	5100	5	113.00	920	25	0.44	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36695	Burro Pass	1400	3	108.02	131	36	0.09	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
3609	Burroaks Dr.	8100	5	116.02	643	26	0.32	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
3610	Burroaks Dr.	8200	5	116.02	515	26	0.25	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
3641	Cabana La.	3800	13	95.00	706	26	0.35	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
3679	Cadiz St.	300	6	33.00	239	44	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
3680	Cadiz St.	400	6	33.00	239	44	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
3681	Cadiz St.	500	6	33.00	239	44	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
3682	Cadiz St.	600	6	33.00	239	44	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
3683	Cadiz St.	700	6	33.00	239	44	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
3684	Cadiz St.	800	2	33.00	239	44	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
3734	Caldwell Av.	1400	7	25.00	650	26	0.32	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
3735	Caldwell Av.	1500	7	25.00	676	20	0.26	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
3736	Caldwell Av.	1600	7	25.00	400	20	0.15	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
31719	Calm Meadow Rd.	6000	12	136.19	650	26	0.32	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
31720	Calm Meadow Rd.	6100	12	136.19	600	26	0.30	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
32314	Cansler Dr.	18100	12	317.98	835	26	0.41	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
32315	Cansler Dr.	18200	12	317.98	300	26	0.15	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999

Street History Improvements 1999-2002

32316	Cansler Dr.	18300	12	317.98	300	26	0.15	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
36809	Canvasback La.	8400	3	165.10	1,036	36	0.71	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
36648	Canyon Ridge Dr.	7100	4	122.02	731	36	0.50	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
3989	Capestone Dr.	6100	5	93.04	685	26	0.34	Asphalt	1970	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
3990	Capestone Dr.	6200	5	93.04	330	26	0.16	Asphalt	1970	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
4110	Carlisle St.	2400	14	18.00	381	26	0.19	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
4111	Carlisle St.	2500	14	18.00	441	32	0.27	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
4113	Carlisle St.	2700	14	18.00	240	32	0.15	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
4114	Carlisle St.	2800	14	18.00	409	32	0.25	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
4115	Carlisle St.	2900	14	18.00	351	32	0.21	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
4206	Carroll Av. (S)	600	2	24.00	440	43	0.36	Concrete		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
4207	Carroll Av. (S)	700	2	25.00	450	30	0.26	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
4208	Carroll Av. (S)	800	2	25.00	344	30	0.20	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
4209	Carroll Av. (S)	900	7	25.00	422	30	0.24	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
4210	Carroll Av. (S)	1000	7	25.00	432	30	0.25	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
4211	Carroll Av. (S)	1100	7	25.00	433	30	0.25	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
36513	Carson Dr.	18400	12	216.10	260	36	0.18	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
4283	Carta Valley Dr.	7300	12	136.05	645	26	0.32	Asphalt	1972	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
4284	Carta Valley Dr.	7400	12	136.05	524	26	0.26	Asphalt	1972	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
4240	Caruth Blvd.	4300	13	73.01	502	26	0.25	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
4241	Caruth Blvd.	4400	13	73.01	494	26	0.24	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
33478	Casablanca Ct.	7100	12	136.07	269	26	0.13	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
4478	Cedar Springs Rd.	4100	14	5.00	560	44	0.47	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
4479	Cedar Springs Rd.	4200	14	5.00	410	44	0.34	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
36799	Cedar Waxwing La.	5300	3	165.01	636	33	0.40	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36730	Cedarbrier Dr.	5000	3	165.01	146	24	0.07	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
4522	Cedarcliff Dr.	500	5	92.02	295	26	0.15	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
4523	Cedarcliff Dr.	600	5	92.02	930	26	0.46	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
36516	Centex Dr.	2500	6	99.00	345	36	0.24	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
32682	Chalk Hill Rd. E	1600	3	107.01	496	48	0.45	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
4653	Chambers St.	4900	2	9.00	410	26	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
4654	Chambers St.	5000	14	9.00	407	26	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
4686	Channing Cir.	900	4	60.02	768	26	0.38	Asphalt	1955	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
36649	Chariot Dr.	7300	4	122.02	292	26	0.14	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
4727	Chateau Av.	9700	5	119.00	450	26	0.22	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
30742	Checota Dr.	9600	5	119.00	450	26	0.22	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
4741	Checota Dr.	10300	5	119.00	635	26	0.31	Concrete	1999	1987	1999	Construction	Construction	Construction	Construction	1999
4741	Checota Dr.	10300	5	119.00	635	26	0.31	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
4742	Checota Dr.	10400	5	119.00	531	26	0.26	Concrete	1999	1987	1999	Construction	Construction	Construction	Construction	1999
4742	Checota Dr.	10400	5	119.00	531	26	0.26	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
4743	Checota Dr.	10500	5	119.00	312	26	0.15	Concrete	1999	1987	1999	Construction	Construction	Construction	Construction	1999
4743	Checota Dr.	10500	5	119.00	312	26	0.15	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
4780	Cherrybrook Dr.	8600	5	92.01	385	26	0.19	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
4781	Cherrybrook Dr.	8700	5	92.01	542	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
4782	Cherrybrook Dr.	8800	5	92.01	382	26	0.19	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
4783	Cherrybrook Dr.	8900	5	92.01	1,023	26	0.50	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
4893	Chimney Corner	9100	11	190.16	285	36	0.19	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
4894	Chimney Corner	9200	11	190.16	285	36	0.19	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
4895	Chimney Corner	9300	11	190.16	273	36	0.19	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
4896	Chimney Corner	9400	11	190.16	264	36	0.18	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
4897	Chimney Corner	9500	11	190.16	263	36	0.18	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
4910	Chimneysweep La.	9200	11	190.16	240	36	0.16	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
4911	Chimneysweep La.	9300	11	190.16	320	36	0.22	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
36815	Christian Ct.	7900	8	109.00	293	26	0.14	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
4956	Cicero St.	4300	4	87.03	491	26	0.24	Concrete	1999	1978	1999	Construction	Construction	Construction	Construction	1999
4956	Cicero St.	4300	4	87.03	491	26	0.24	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
4957	Cicero St.	4400	4	87.03	635	26	0.31	Concrete	1999	1978	1999	Construction	Construction	Construction	Construction	1999
4957	Cicero St.	4400	4	87.03	635	26	0.31	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999

Street History Improvements 1999-2002

4958	Cinnamon Oaks Dr.	6300	8	167.01	785	26	0.39	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
4959	Cinnamon Oaks Dr.	6400	8	167.01	699	26	0.34	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
4960	Cinnamon Oaks Dr.	6500	8	167.01	681	26	0.34	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
5016	Clarendon Dr. (E)	800	6	41.00	558	56	0.59	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
5017	Clarendon Dr. (E)	900	6	41.00	668	56	0.71	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
5018	Clarendon Dr. (E)	1000	6	41.00	526	56	0.56	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
5038	Clarendon Dr. (W)	1400	1	52.00	390	38	0.28	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
5039	Clarendon Dr. (W)	1500	1	52.00	428	38	0.31	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
5040	Clarendon Dr. (W)	1600	1	52.00	353	38	0.25	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
5064	Clark St.	2300	14	17.02	333	30	0.19	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
5126	Clearhaven Dr.	7100	12	136.05	551	26	0.27	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
5127	Clearhaven Dr.	7200	12	136.05	592	26	0.29	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
5128	Clearhaven Dr.	7300	12	136.05	600	26	0.30	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
5129	Clearhaven Dr.	7400	12	136.05	570	26	0.28	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
36507	Clearhurst Dr.	9000	10	130.04	362	30	0.21	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
36508	Clearhurst Dr.	9100	10	130.04	407	30	0.23	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
5172	Clements St.	3500	14	2.01	380	26	0.19	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
5173	Clements St.	3600	14	2.01	304	26	0.15	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
5174	Clements St.	3700	14	2.01	280	26	0.14	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
5218	Cliffbrook Dr.	6400	11	136.08	835	26	0.41	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
5219	Cliffbrook Dr.	6500	11	136.08	1,040	26	0.51	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
5220	Cliffbrook Dr.	6600	11	136.08	380	26	0.19	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
5221	Cliffbrook Dr.	6700	11	136.08	420	26	0.21	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
5222	Cliffbrook Dr.	6800	11	136.08	582	26	0.29	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
30763	Club Meadows Dr.	8200	10	78.12	1,085	26	0.53	Asphalt	1977	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
30764	Club Meadows Dr.	8300	10	78.12	743	26	0.37	Asphalt	1977	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
30765	Club Meadows Dr.	8400	10	78.12	320	33	0.20	Asphalt	1977	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
36803	Cockatiel La.	5300	3	165.01	641	33	0.40	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36704	Cockrell Hill Rd. (N)	600	3	107.01	571	70	0.76	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36705	Cockrell Hill Rd. (N)	700	3	107.01	561	70	0.74	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36706	Cockrell Hill Rd. (N)	800	3	107.01	561	70	0.74	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36707	Cockrell Hill Rd. (N)	900	3	107.01	561	70	0.74	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36708	Cockrell Hill Rd. (N)	1000	3	107.01	561	70	0.74	Asphalt	2001		2001	Construction	Construction	Construction	Construction	2001
36709	Cockrell Hill Rd. (N)	1100	3	107.01	561	70	0.74	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36710	Cockrell Hill Rd. (N)	1200	3	107.01	561	70	0.74	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36711	Cockrell Hill Rd. (N)	1300	3	107.01	561	70	0.74	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36712	Cockrell Hill Rd. (N)	1400	3	107.01	564	70	0.75	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36713	Cockrell Hill Rd. (N)	1500	3	107.01	565	70	0.75	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36714	Cockrell Hill Rd. (N)	1600	3	107.01	370	70	0.49	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
5447	Coit Rd.	13500	12	136.10	623	66	0.78	Asphalt		2000	2000	County	Resurfacing	Other Project	County	2000
5448	Coit Rd.	13600	12	136.10	637	66	0.80	Asphalt		2000	2000	County	Resurfacing	Other Project	County	2000
5449	Coit Rd.	13700	12	136.10	305	66	0.38	Asphalt		2000	2000	County	Resurfacing	Other Project	County	2000
5450	Coit Rd.	13800	12	136.10	317	66	0.40	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
5451	Coit Rd.	13900	12	136.10	310	66	0.39	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
5452	Coit Rd.	14000	12	136.10	651	66	0.81	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
33489	Colada Ct.	7100	12	136.07	290	26	0.14	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
5566	Colonial Av.	4700	7	40.00	223	40	0.17	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
5567	Colonial Av.	4800	7	40.00	242	40	0.18	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
5568	Colonial Av.	4900	7	40.00	229	40	0.17	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
5641	Comer Dr.	8600	5	92.01	560	26	0.28	Asphalt	1958	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
5642	Comer Dr.	8700	5	92.01	745	26	0.37	Asphalt	1958	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
5643	Comer Dr.	8800	5	92.01	400	26	0.20	Asphalt	1958	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
5644	Comer Dr.	8900	5	92.01	337	26	0.17	Asphalt	1958	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
5681	Commerce St.	4000	2	31.02	431	40	0.33	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
5682	Commerce St.	4100	7	28.00	775	40	0.59	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
5683	Commerce St. (W)	100	1	100.00	783	60	0.89	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
5683	Commerce St. (W)	100	1	43.00	2,728	60	3.10	Asphalt		1999	1999	1998 Bridge Repair	Resurfacing	95 Bond	Bridge	1998
5684	Commerce St. (W)	200	1	43.00	903	60	1.03	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002

Street History Improvements 1999-2002

5685	Commerce St. (W)	300	1	43.00	540	60	0.61	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
5686	Commerce St. (W)	400	1	43.00	950	60	1.08	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
5687	Commerce St. (W)	500	1	43.00	400	24	0.18	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
36808	Concordant Trl.	2500	8	109.00	6,750	26	3.32	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
5781	Conner Dr.	1300	5	92.01	525	40	0.40	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
5782	Conner Dr.	1400	5	92.01	761	40	0.58	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
5808	Continental Viad. (W)	100	6	100.00	1,910	48	1.74	Asphalt		1999	1999	1998 Bridge Repair	Resurfacing	95 Bond	Bridge	1998
31242	Cooper St.	1600	7	40.00	123	26	0.06	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
5875	Cooper St.	1700	7	40.00	387	26	0.19	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
5894	Coppedge La.	9900	14	94.01	1,305	26	0.64	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
5915	Corbin St.	600	2	21.00	265	58	0.29	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
5935	Corinth St.	200	2	33.00	215	40	0.16	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
5936	Corinth St.	300	2	33.00	215	40	0.16	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
5937	Corinth St.	400	2	33.00	214	40	0.16	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
5938	Corinth St.	500	6	33.00	214	40	0.16	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
35153	Corinth St.	600	6	33.00	325	44	0.27	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
35154	Corinth St.	700	2	33.00	325	44	0.27	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
5939	Corinth St.	800	2	33.00	325	44	0.27	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
5940	Corinth St.	900	2	33.00	325	44	0.27	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
5941	Corinth St.	1000	2	33.00	268	60	0.30	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
5983	Cork La.	9100	10	78.13	747	26	0.37	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
34725	Coxville La.	400	8	170.02	1,042	30	0.59	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
35742	Coxville La.	500	8	170.02	707	30	0.40	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
6150	Craige Dr.	8600	5	92.01	850	26	0.42	Asphalt	1958	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
6151	Craige Dr.	8700	5	92.01	860	26	0.42	Asphalt	1958	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
6152	Craige Dr.	8800	5	92.01	374	26	0.18	Asphalt	1958	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
6153	Craige Dr.	8900	5	92.01	320	26	0.16	Asphalt	1958	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
31256	Crawford St. (N)	1000	1	20.00	370	40	0.28	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
31257	Crawford St. (N)	1100	1	20.00	520	40	0.39	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
6249	Crest Brook Dr.	11300	11	133.00	710	26	0.35	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
6250	Crest Brook Dr.	11400	11	133.00	510	26	0.25	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
6245	Crest Ridge Dr.	3000	9	125.00	546	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
6246	Crest Ridge Dr.	3100	9	125.00	410	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
6247	Crest Ridge Dr.	3200	9	125.00	510	26	0.25	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
6248	Crest Ridge Dr.	3300	9	125.00	699	26	0.34	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
32285	Crested Butte Dr.	6200	12	317.98	530	26	0.26	Asphalt	1980	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
32286	Crested Butte Dr.	6300	12	317.98	530	26	0.26	Asphalt	1980	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
6295	Crestmere Dr.	6500	11	136.08	1,014	26	0.50	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
6315	Crestway Dr.	6500	11	132.00	400	26	0.20	Asphalt	1966	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
6316	Crestway Dr.	6600	11	132.00	478	26	0.24	Asphalt	1966	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
6324	Crim Dr.	12800	11	132.00	375	26	0.18	Asphalt	1953	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
6325	Crim Dr.	12900	11	132.00	375	26	0.18	Asphalt	1953	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
33836	Crownover Ct.	18500	12	317.98	410	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
33837	Crownover Ct.	18600	12	317.98	550	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
6447	Crusader Dr.	300	8	117.00	1,190	26	0.59	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
6448	Crusader Dr.	400	8	117.00	160	26	0.08	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
6530	Dairy Milk La.	2800	2	97.01	1,000	36	0.68	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
6576	Danbury La.	6000	9	79.05	303	36	0.21	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
36517	Dandy La.	7600	4	91.01	820	26	0.40	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
36518	Danfield Ct.	7500	12	317.98	250	30	0.14	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
6618	Danube Dr.	1500	6	49.00	395	26	0.19	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
6621	Danube Dr.	1800	6	55.00	603	28	0.32	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
6622	Danube Dr.	1900	6	55.00	439	28	0.23	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
6624	Danvers Pl.	13700	11	136.08	200	26	0.10	Asphalt	1956	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
6628	Danville Dr.	8600	5	92.01	704	26	0.35	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
6629	Danville Dr.	8700	5	92.01	491	26	0.24	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
6630	Danville Dr.	8800	5	92.01	1,251	26	0.62	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
33880	Davenport Rd.	18100	12	317.98	515	36	0.35	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999

Street History Improvements 1999-2002

33881	Davenport Rd.	18200	12	317.98	574	36	0.39	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
33882	Davenport Rd.	18300	12	317.98	600	36	0.41	Concrete		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
6745	Davis St. (W)	3300	1	68.00	436	60	0.50	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
6746	Davis St. (W)	3400	1	68.00	440	60	0.50	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
6747	Davis St. (W)	3500	1	68.00	430	60	0.49	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
6748	Davis St. (W)	3600	1	68.00	270	36	0.18	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
35915	Davis St. (W)	3700	1	68.00	440	36	0.30	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
32329	Debbe Dr.	7100	12	317.98	790	26	0.39	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
6853	Deer Trail Pl.	7700	10	130.04	261	26	0.13	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
6875	Del Norte La.	6600	13	77.00	550	26	0.27	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
6876	Del Norte La.	6700	13	77.00	424	36	0.29	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
6877	Del Norte La.	6800	13	77.00	434	36	0.30	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
6924	Delford Cir.	11000	9	126.02	860	26	0.42	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
6937	Delrose Dr.	6900	9	80.00	727	26	0.36	Concrete	1999	1975	1999	Construction	Construction	Construction	Construction	1999
6937	Delrose Dr.	6900	9	80.00	727	26	0.36	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
6938	Delrose Dr.	7000	9	80.00	631	26	0.31	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
36520	Derby La.	4800	4	122.02	410	36	0.28	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
7185	Desco Dr.	7100	13	78.01	320	26	0.16	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
7186	Desco Dr.	7200	13	78.01	410	26	0.20	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
7257	Dilbeck La.	6000	11	136.08	612	26	0.30	Asphalt	1960	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
7258	Dilbeck La.	6100	11	136.08	612	26	0.30	Asphalt	1960	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
7259	Dilbeck La.	6200	11	136.08	595	26	0.29	Asphalt	1960	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
36715	Doe St.	5700	3	165.10	118	40	0.09	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
7428	Douglas Av.	2700	14	5.00	466	30	0.26	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
7429	Douglas Av.	2800	14	5.00	270	30	0.15	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
7430	Douglas Av.	2900	14	5.00	248	30	0.14	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
7431	Douglas Av.	3000	14	5.00	465	30	0.26	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
7405	Douglas Av.	4100	14	6.03	583	22	0.24	Asphalt	1949	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
7406	Douglas Av.	4200	14	6.03	340	30	0.19	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
7407	Douglas Av.	4300	14	6.03	335	30	0.19	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
7408	Douglas Av.	4400	14	6.03	340	30	0.19	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
7409	Douglas Av.	4500	14	6.03	180	30	0.10	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
36725	Dove Dr.	5400	3	165.01	439	33	0.27	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36726	Dove Dr.	5500	3	165.01	438	33	0.27	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
7661	Durango Dr.	3500	2	98.02	788	26	0.39	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
7663	Durango Dr.	3700	14	94.01	944	26	0.46	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
7710	Dwight Av. (N)	1000	3	107.01	535	26	0.26	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
7711	Dwight Av. (N)	1100	3	107.01	391	26	0.19	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
7720	Dykes Wy.	6200	11	132.00	880	26	0.43	Asphalt	1953	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
7721	Dykes Wy.	6300	11	132.00	375	26	0.18	Asphalt	1953	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
7722	Dykes Wy.	6400	11	132.00	405	26	0.20	Asphalt	1953	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
36794	Dynasty Dr.	7600	8	167.02	410	44	0.34	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36795	Dynasty Dr.	7700	8	167.02	410	44	0.34	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
7849	Easton Rd.	700	9	129.00	800	44	0.67	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
7849	Easton Rd.	700	9	129.00	800	44	0.67	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
7850	Easton Rd.	800	9	82.00	1,697	44	1.41	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
7851	Easton Rd.	900	9	82.00	1,581	44	1.32	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
7852	Easton Rd.	1000	9	82.00	250	44	0.21	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
7853	Easton Rd.	1100	9	82.00	1,135	44	0.95	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
7873	Eastwood Dr.	10100	9	124.00	755	26	0.37	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	95 Bond	2010	2000
7892	Echo Bluff Dr.	6900	12	136.19	1,235	26	0.61	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
7893	Echo Bluff Dr.	7000	12	136.19	180	26	0.09	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
7904	Eden Valley La.	8300	5	92.02	675	26	0.33	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
7905	Eden Valley La.	8400	5	92.02	676	26	0.33	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
7978	Edgeglen Dr.	600	8	118.00	806	26	0.40	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
7979	Edgeglen Dr.	700	8	118.00	550	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
7986	Edgemere Rd.	8700	13	77.00	760	36	0.52	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
7987	Edgemere Rd.	8800	13	77.00	307	36	0.21	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002

Street History Improvements 1999-2002

7988	Edgemere Rd.	8900	13	77.00	340	36	0.23	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
7989	Edgemere Rd.	9000	13	77.00	358	36	0.24	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
7990	Edgemere Rd.	9100	13	77.00	415	36	0.28	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
7991	Edgemere Rd.	9200	13	77.00	438	36	0.30	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
7992	Edgemere Rd.	9300	13	77.00	420	36	0.29	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
7993	Edgemere Rd.	9400	13	77.00	435	36	0.30	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
8013	Edgemont Av.	300	6	54.00	889	26	0.44	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000	
8014	Edgemont Av.	400	6	54.00	325	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000	
8015	Edgemont Av.	500	6	54.00	349	26	0.17	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000	
8112	Eisenhower Dr.	2900	6	56.00	615	26	0.30	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000	
8113	Eisenhower Dr.	3000	6	56.00	630	26	0.31	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000	
8170	Elam Heights Dr.	8500	5	92.02	704	26	0.35	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999	
8171	Elam Heights Dr.	8600	5	92.02	423	26	0.21	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999	
8177	Elam Rd.	6100	5	93.03	690	36	0.47	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
8178	Elam Rd.	6200	5	93.03	691	36	0.47	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
8179	Elam Rd.	6300	5	93.03	712	36	0.49	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
8180	Elam Rd.	6400	5	93.03	587	36	0.40	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
8181	Elam Rd.	6500	5	93.03	371	36	0.25	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
8182	Elam Rd.	6600	5	93.03	538	36	0.37	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
8183	Elam Rd.	6700	5	93.03	355	36	0.24	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
8184	Elam Rd.	6800	5	93.03	355	36	0.24	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002	
8228	Elderleaf Dr.	1900	5	111.01	750	26	0.37	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999	
8229	Elderoaks La.	2000	5	111.01	345	26	0.17	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999	
8230	Elderoaks La.	2100	5	111.01	335	26	0.16	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999	
8231	Elderoaks La.	2200	5	111.01	700	26	0.34	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999	
8232	Elderoaks La.	2300	5	111.01	420	26	0.21	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999	
8233	Elderoaks Pl.	2100	5	111.01	375	26	0.18	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999	
8261	Eleventh St. (E)	1600	6	89.00	335	40	0.25	Concrete	2000	1979	2000	Construction	Construction	Construction	Construction	2000	
8261	Eleventh St. (E)	1600	6	89.00	335	40	0.25	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000	
8262	Eleventh St. (E)	1700	6	89.00	290	40	0.22	Concrete	2000	1979	2000	Construction	Construction	Construction	Construction	2000	
8262	Eleventh St. (E)	1700	6	89.00	290	40	0.22	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000	
8263	Eleventh St. (E)	1800	6	89.00	400	40	0.30	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000	
8263	Eleventh St. (E)	1800	6	89.00	400	40	0.30	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000	
8264	Eleventh St. (E)	1900	6	89.00	160	40	0.12	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000	
8264	Eleventh St. (E)	1900	6	89.00	160	40	0.12	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000	
8265	Eleventh St. (E)	2000	6	89.00	130	40	0.10	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000	
8265	Eleventh St. (E)	2000	6	89.00	130	40	0.10	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000	
8298	Elkton Cir.	8100	5	116.02	549	26	0.27	Asphalt		1958	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
8299	Elkton Cir.	8200	5	116.02	470	26	0.23	Asphalt		1958	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
8300	Ella Av.	300	5	93.04	950	26	0.47	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999	
8301	Ella Av.	400	5	93.04	925	36	0.63	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999	
8349	Elm St.	1500	2	31.01	364	52	0.36	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001	
8350	Elm St.	1600	2	31.01	424	52	0.42	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001	
8351	Elm St.	1700	2	31.01	213	52	0.21	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001	
8352	Elm St.	1800	2	31.01	213	52	0.21	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001	
8353	Elm St.	1900	2	31.01	489	52	0.48	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001	
8354	Elm St.	2000	2	31.01	316	52	0.31	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001	
8355	Elm St.	2100	2	31.01	260	52	0.26	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001	
8359	Elm St.	2500	2	31.02	877	44	0.73	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002	
8360	Elm St.	2600	2	31.02	554	40	0.42	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002	
8361	Elm St.	2700	2	31.02	340	50	0.32	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002	
8362	Elm St.	2800	2	31.02	365	50	0.35	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002	
8363	Elm St.	2900	2	31.02	490	50	0.46	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002	
8364	Elm St.	3000	2	31.02	550	50	0.52	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002	
8365	Elm St.	3100	2	31.02	224	44	0.19	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002	
8366	Elm St.	3200	2	31.02	224	44	0.19	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002	
8367	Elm St.	3300	2	31.02	548	44	0.46	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002	
8368	Elm St.	3400	2	31.02	202	44	0.17	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002	

Street History Improvements 1999-2002

8369	Elm St.	3700	2	22.02	300	40	0.23	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
8370	Elm St.	3800	2	22.02	300	40	0.23	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
8371	Elm St.	3900	2	22.02	543	40	0.41	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
8372	Elm St.	4000	2	22.02	438	40	0.33	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
8373	Elm St.	4100	2	15.02	350	40	0.27	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
8374	Elm St.	4200	2	15.02	350	40	0.27	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
8375	Elm St.	4300	2	15.02	340	36	0.23	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
8376	Elm St.	4400	2	15.02	348	36	0.24	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
8420	Elmore Av. (E)	1400	6	55.00	335	30	0.19	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
8421	Elmore Av. (E)	1500	6	55.00	1,047	30	0.59	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
8608	Emberglow La.	9000	11	190.16	258	36	0.18	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8609	Emberglow La.	9100	11	190.16	240	36	0.16	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8610	Emberglow La.	9200	11	190.16	427	36	0.29	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8611	Emberglow La.	9300	11	190.16	329	36	0.22	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8670	Estacado Dr.	10000	9	124.00	415	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8671	Estacado Dr.	10100	9	124.00	860	26	0.42	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8672	Estacado Dr.	10200	9	124.00	800	26	0.39	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8673	Estacado Dr.	10300	9	124.00	906	26	0.45	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8707	Eudora Dr.	7000	11	131.01	553	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8708	Eudora Dr.	7100	11	131.01	640	26	0.32	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8709	Eudora Dr.	7200	11	131.01	730	26	0.36	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8755	Ewing Av. (N)	100	1	48.00	315	30	0.18	Asphalt	1957	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
8756	Ewing Av. (N)	200	1	48.00	628	30	0.36	Asphalt	1957	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
8770	Ewing Av. (S)	700	6	54.00	335	36	0.23	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
8771	Ewing Av. (S)	800	6	54.00	381	36	0.26	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
8778	Ewing Av. (S)	1500	6	54.00	672	36	0.46	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
8779	Ewing Av. (S)	1600	6	54.00	271	36	0.18	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
8780	Ewing Av. (S)	1700	6	54.00	288	36	0.20	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
8837	Ezekial Av.	500	5	93.03	862	26	0.42	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
8837	Ezekial Av.	500	5	93.03	862	26	0.42	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
8838	Ezekial Av.	600	5	93.03	848	26	0.42	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
8838	Ezekial Av.	600	5	93.03	848	26	0.42	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
8839	Ezekial Av.	700	5	93.03	914	26	0.45	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
8839	Ezekial Av.	700	5	93.03	914	26	0.45	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
34429	Fair Oaks Crsg.	8400	10	78.11	510	33	0.32	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
34757	Fair Oaks Crsg.	8500	10	78.11	450	33	0.28	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
33520	Fair Oaks Crsg.	8600	10	78.11	165	33	0.10	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
33521	Fair Oaks Crsg.	8700	10	78.11	165	33	0.10	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
31779	Fair Oaks Crsg.	8800	10	78.11	1,112	33	0.70	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
30856	Faircloud Dr.	9700	5	119.00	1,095	26	0.54	Asphalt		2000	2000	DWU	Resurfacing	DWU	DWU	2000
8899	Fairhope Av.	9400	8	117.00	630	26	0.31	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
8909	Fairmount St.	2400	14	17.02	339	34	0.22	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
8914	Fairmount St.	2900	14	18.00	349	38	0.25	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8915	Fairmount St.	3000	14	18.00	296	38	0.21	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8916	Fairmount St.	3100	14	18.00	236	38	0.17	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8917	Fairmount St.	3200	14	18.00	422	38	0.30	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8918	Fairmount St.	3300	14	5.00	464	40	0.35	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
8919	Fairmount St.	3400	14	5.00	320	40	0.24	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
8920	Fairmount St.	3500	14	5.00	507	40	0.38	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
8921	Fairmount St.	3600	14	5.00	420	40	0.32	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
8922	Fairmount St.	3700	14	5.00	316	40	0.24	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
36526	Fairmount St.	4800	2	4.04	150	26	0.07	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
8933	Fairport Rd.	7500	8	116.01	325	20	0.12	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
8934	Fairport Rd.	7600	8	116.01	325	24	0.15	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
8935	Fairport Rd.	7700	8	116.01	608	26	0.30	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
8936	Fairport Rd.	7800	8	116.01	311	26	0.15	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
8937	Fairport Rd.	7900	8	116.01	561	26	0.28	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
8952	Fairview Av.	3000	7	25.00	369	36	0.25	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999

Street History Improvements 1999-2002

8953	Fairview Av.	3100	7	25.00	369	36	0.25	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
8954	Fairview Av.	3200	7	25.00	725	36	0.49	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
8955	Fairview Av.	3300	7	25.00	250	36	0.17	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
8956	Fairview Av.	3400	7	25.00	623	36	0.42	Concrete	1999	1978	1999	Construction	Construction	Construction	Construction	1999
8956	Fairview Av.	3400	7	25.00	623	36	0.42	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
8957	Fairview Av.	3500	7	25.00	552	36	0.38	Concrete	1999	1978	1999	Construction	Construction	Construction	Construction	1999
8957	Fairview Av.	3500	7	25.00	552	36	0.38	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
35774	Fairway Av.	6300	7	84.00	160	26	0.08	Asphalt		2000	2000	DWU	Resurfacing	DWU	DWU	2000
35775	Featherwood Dr.	18200	12	317.98	270	26	0.13	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
32361	Featherwood Dr.	18300	12	317.98	290	26	0.14	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
32362	Featherwood Dr.	18400	12	317.98	590	26	0.29	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
32363	Featherwood Dr.	18500	12	317.98	560	26	0.28	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
32364	Featherwood Dr.	18600	12	317.98	580	26	0.29	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9119	Ferguson Rd.	7800	7	122.03	670	60	0.76	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9120	Ferguson Rd.	7900	7	122.03	350	60	0.40	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9121	Ferguson Rd.	8000	7	122.03	900	60	1.02	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9122	Ferguson Rd.	8100	7	122.03	800	60	0.91	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9123	Ferguson Rd.	8200	7	122.03	1,050	60	1.19	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9124	Ferguson Rd.	8300	7	122.03	800	60	0.91	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9125	Ferguson Rd.	8400	7	122.03	700	60	0.80	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9126	Ferguson Rd.	8500	7	122.03	1,150	60	1.31	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9127	Ferguson Rd.	8600	9	122.03	460	60	0.52	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9128	Ferguson Rd.	8700	9	122.03	460	60	0.52	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9129	Ferguson Rd.	8800	9	122.03	460	60	0.52	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9130	Ferguson Rd.	8900	9	122.03	371	60	0.42	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9131	Ferguson Rd.	9000	9	122.03	402	60	0.46	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9132	Ferguson Rd.	9100	9	122.03	646	60	0.73	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9144	Ferguson Rd.	10300	9	127.00	820	66	1.03	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9145	Ferguson Rd.	10400	9	127.00	1,204	66	1.51	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9146	Ferguson Rd.	10500	9	127.00	1,086	66	1.36	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9147	Ferguson Rd.	10600	9	127.00	400	66	0.50	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9148	Ferguson Rd.	10700	9	127.00	310	66	0.39	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9149	Ferguson Rd.	10800	10	126.01	910	66	1.14	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9223	Fernmeadow Cir.	7100	12	136.07	275	26	0.14	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
9224	Fernmeadow Dr.	7200	12	136.07	1,098	26	0.54	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
9281	Field St. (N)	2100	2	19.00	325	66	0.41	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
9282	Field St. (N)	2200	2	19.00	300	66	0.38	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
9339	Fifty-Second St.	2100	5	87.04	639	26	0.31	Asphalt	1958	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
9340	Fifty-Second St.	2200	5	87.04	635	26	0.31	Asphalt	1958	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
9341	Fifty-Second St.	2300	5	87.04	1,819	36	1.24	Asphalt	1959	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
9342	Fifty-Second St.	2400	5	87.04	555	26	0.27	Asphalt	1985	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
9355	Fifty-sixth St.	2700	8	87.05	466	24	0.21	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
9355	Fifty-Sixth St.	2700	8	87.05	466	24	0.21	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
9356	Fifty-sixth St.	2800	8	87.05	1,032	24	0.47	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
9356	Fifty-Sixth St.	2800	8	87.05	1,032	24	0.47	Concrete	2000	1977	2000	Construction	Construction	Construction	Construction	2000
36528	Finnell St.	10300	6	99.00	1,015	36	0.69	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
36529	Finnell St.	10400	6	99.00	495	36	0.34	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
9369	Firelog La.	9200	11	190.16	655	36	0.45	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9408	Fisher Rd.	6100	9	79.03	515	40	0.39	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9409	Fisher Rd.	6200	9	79.03	515	40	0.39	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9410	Fisher Rd.	6300	9	79.03	515	40	0.39	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9455	Fitzhugh Av. (N)	2900	2	9.00	586	66	0.73	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
9455	Fitzhugh Av. (N)	2900	2	9.00	586	66	0.73	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
9512	Five Mile Pkwy. (W)	1500	6	61.00	430	26	0.21	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
9513	Five Mile Pkwy. (W)	1600	6	61.00	1,270	26	0.63	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
9515	Five Mile Pkwy. (W)	1800	6	61.00	390	26	0.19	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
9516	Five Mile Pkwy. (W)	1900	6	61.00	390	26	0.19	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
9532	Flagstone La.	13600	11	192.08	604	36	0.41	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001

Street History Improvements 1999-2002

9533	Flagstone La.	13700	11	192.08	606	36	0.41	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
33921	Flanary La.	6600	12	317.98	940	26	0.46	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9575	Flickering Shadow Dr.	9200	11	190.16	790	36	0.54	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9692	Fordham Rd.	1900	4	57.00	922	36	0.63	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
9790	Forest La.	5700	13	96.04	550	60	0.63	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
9791	Forest La.	5800	13	96.04	500	60	0.57	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
9792	Forest La.	5900	13	96.04	950	60	1.08	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
9856	Forest Pkwy.	7000	8	167.01	1,202	26	0.59	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
9857	Forest Pkwy.	7100	8	167.01	585	26	0.29	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
9858	Forest Pkwy.	7200	8	167.01	600	26	0.30	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
9877	Forestway Dr.	13300	11	136.08	200	26	0.10	Asphalt	1962	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9878	Forestway Dr.	13400	11	136.08	670	26	0.33	Asphalt	1962	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
33925	Fortson Av.	18500	12	317.98	555	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
33926	Fortson Av.	18600	12	317.98	430	26	0.21	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
9979	Foxworth Dr.	7200	12	136.05	555	26	0.27	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9980	Foxworth Dr.	7300	12	136.05	540	26	0.27	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
9981	Foxworth Dr.	7400	12	136.05	580	26	0.29	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
35654	Frankford Rd. (S)	7300	12	317.98	560	20	0.21	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
10054	Freddie St.	200	5	117.00	1,246	27	0.64	Asphalt	1955	2002	2002	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
10055	Freddie St.	300	5	117.00	616	27	0.32	Asphalt	1955	2002	2002	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
36824	Friendway La.	2500	8	109.00	795	26	0.39	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
10264	Gano St.	1700	2	33.00	637	26	0.31	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
10265	Gano St.	1800	2	33.00	238	26	0.12	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
10325	Garland Rd.	8100	9	81.00	670	60	0.76	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
10326	Garland Rd.	8200	9	81.00	879	60	1.00	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
10327	Garland Rd.	8300	9	81.00	1,070	60	1.22	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
10328	Garland Rd.	8400	9	81.00	880	60	1.00	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
10329	Garland Rd.	8500	9	81.00	940	60	1.07	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
10330	Garland Rd.	8600	9	81.00	600	60	0.68	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
10331	Garland Rd.	8700	9	81.00	600	60	0.68	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
10332	Garland Rd.	8800	9	81.00	300	60	0.34	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
10333	Garland Rd.	8900	9	81.00	545	60	0.62	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
10334	Garland Rd.	9000	9	81.00	640	60	0.73	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
10335	Garland Rd.	9100	9	81.00	754	60	0.86	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
10336	Garland Rd.	9200	9	81.00	650	60	0.74	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
10337	Garland Rd.	9300	9	81.00	680	60	0.77	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
10338	Garland Rd.	9400	9	81.00	605	60	0.69	Asphalt		2000	2000	2000 County	Resurfacing	Other Project	2000 County	2000
32376	Garlinghouse La.	6600	12	317.98	975	26	0.48	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
10388	Garrison St.	3000	4	88.02	220	36	0.15	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	95 Bond	2010	2000
10389	Garrison St.	3100	4	88.02	317	36	0.22	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	95 Bond	2010	2000
10390	Garrison St.	3200	4	88.02	316	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	95 Bond	2010	2000
10391	Garrison St.	3300	4	88.02	337	26	0.17	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	95 Bond	2010	2000
10392	Garrison St.	3400	4	88.02	397	26	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	95 Bond	2010	2000
10393	Garrison St.	3500	4	88.02	304	26	0.15	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	95 Bond	2010	2000
10419	Garza Av.	1500	4	57.00	581	20	0.22	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
34771	Gaston Pkwy.	9200	9	81.00	226	26	0.11	Asphalt		2000	2000	Other Project	Resurfacing	Other Project	Other Project	2000
10505	Gaylen Dr.	7100	5	116.01	700	36	0.48	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
34454	Gaylen Dr.	7200	5	116.01	450	26	0.22	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
36531	Gaylord Dr.	2300	4	91.01	802	26	0.39	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
10544	Georgia Av.	700	6	54.00	335	22	0.14	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
10576	Gilbert Av.	3700	14	6.04	804	28	0.43	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
10805	Glenhurst Dr.	6600	11	136.08	741	26	0.36	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
10806	Glenhurst Dr.	6700	11	136.08	482	26	0.24	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
36716	Glenway Dr.	7900	3	165.10	1,185	40	0.90	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
31831	Golden Creek Rd.	15800	12	136.19	517	26	0.25	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
31832	Golden Creek Rd.	15900	12	136.19	549	26	0.27	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
31833	Golden Creek Rd.	16000	12	136.19	286	26	0.14	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
31834	Golden Creek Rd.	16100	12	136.19	860	26	0.42	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000

## Street History Improvements 1999-2002

31835	Golden Creek Rd.	16200	12	136.19	281	26	0.14	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
31836	Golden Creek Rd.	16300	12	136.19	275	26	0.14	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
10989	Gorman St.	2000	7	25.00	321	26	0.16	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11003	Gracefield La.	7100	12	136.05	960	36	0.65	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
11004	Gracefield La.	7200	12	136.05	480	36	0.33	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
36534	Granbury Dr.	3600	12	216.10	260	36	0.18	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
36535	Granbury Dr.	3700	12	216.10	650	36	0.44	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
31319	Graystone Dr.	17000	12	136.18	600	26	0.30	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
31320	Graystone Dr.	17100	12	136.18	300	26	0.15	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
31321	Graystone Dr.	17200	12	136.18	1,000	26	0.49	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
11147	Greenbrier Dr.	5500	13	73.01	523	26	0.26	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
11148	Greenbrier Dr.	5600	13	73.01	595	26	0.29	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
36717	Greengate Dr.	7900	3	165.10	914	40	0.69	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
11163	Greenhaven Dr.	200	5	93.04	606	26	0.30	Asphalt	1956	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
11164	Greenhaven Dr.	300	5	93.04	400	26	0.20	Asphalt	1956	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
11165	Greenhaven Dr.	400	5	93.04	275	26	0.14	Asphalt	1956	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
11184	Greenport Dr.	2400	7	122.04	485	26	0.24	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
11185	Greenport Dr.	2500	7	122.04	515	26	0.25	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
11447	Grovecrest Dr.	8300	5	92.01	658	26	0.32	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11448	Grovecrest Dr.	8400	5	92.01	633	26	0.31	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11449	Grovecrest Dr.	8500	5	92.01	313	26	0.15	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11450	Grovecrest Dr.	8600	5	92.01	680	26	0.33	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11451	Grovecrest Dr.	8700	5	92.01	636	26	0.31	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11452	Grovecrest Dr.	8800	5	92.01	535	26	0.26	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11453	Grovecrest Dr.	8900	5	92.01	505	26	0.25	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11466	Groveridge Dr.	2700	5	120.00	1,072	26	0.53	Asphalt	1965	2002	2002	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
11490	Guillot St.	2700	14	17.02	268	30	0.15	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
11491	Guillot St.	2800	14	17.02	260	30	0.15	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
11501	Gunter Av.	3200	7	28.00	504	30	0.29	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
11544	Guthrie St.	100	6	56.00	555	30	0.32	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
11625	Hall St. (N)	2100	14	16.00	322	80	0.49	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
11626	Hall St. (N)	2200	14	17.02	94	40	0.07	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
11695	Hamilton Av.	4600	7	25.00	209	26	0.10	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11696	Hamilton Av.	4700	7	25.00	490	26	0.24	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11697	Hamilton Av.	4800	7	25.00	140	26	0.07	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11724	Hampton Rd. (N)	500	3	45.00	366	60	0.42	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
11725	Hampton Rd. (N)	600	1	68.00	575	66	0.72	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
11726	Hampton Rd. (N)	700	1	68.00	430	66	0.54	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
11727	Hampton Rd. (N)	800	1	68.00	1,250	66	1.56	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11728	Hampton Rd. (N)	900	1	68.00	570	66	0.71	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11729	Hampton Rd. (N)	1000	3	68.00	342	66	0.43	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
11764	Hampton Rd. (S)	500	1	53.00	375	60	0.43	Asphalt	1967	2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
11765	Hampton Rd. (S)	600	1	53.00	383	60	0.44	Asphalt	1967	2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
11766	Hampton Rd. (S)	700	1	53.00	387	60	0.44	Asphalt	1967	2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
11769	Hampton Rd. (S)	1000	1	53.00	412	60	0.47	Asphalt	1967	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
11770	Hampton Rd. (S)	1100	1	53.00	640	60	0.73	Asphalt	1967	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
11771	Hampton Rd. (S)	1200	1	53.00	352	60	0.40	Asphalt	1967	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
32775	Harbinger La.	2600	12	216.09	600	26	0.30	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
11968	Harry Hines Blvd.	2400	14	19.00	382	56	0.41	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
12225	Haskell Av. (N)	3100	14	7.01	438	40	0.33	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
12226	Haskell Av. (N)	3200	14	7.01	398	26	0.20	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
12550	Helslem Wy.	6900	11	132.00	850	26	0.42	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
12551	Helslem Wy.	7000	11	132.00	500	26	0.25	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
36537	Hermosillo Plz.	2500	3	108.01	90	22	0.04	Concrete	1999		1999	Construction	Private Construction	Private Construction	Development	1999
36732	Heron Trl.	5300	3	165.01	632	33	0.40	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
12627	High Point Cir.	12200	10	78.04	878	26	0.43	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
12643	High Vista Dr.	3700	13	96.08	1,402	36	0.96	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
34463	Highland Heather La.	7100	12	317.98	327	26	0.16	Asphalt	1981	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001

## Street History Improvements 1999-2002

33162	Highland Heather La.	7200	12	317.98	410	26	0.20	Asphalt	1981	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
33163	Highland Heather La.	7300	12	317.98	770	26	0.38	Asphalt	1981	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
12681	Highland Hills Dr.	5900	8	114.01	800	36	0.55	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
12682	Highland Hills Dr.	6000	8	114.01	625	36	0.43	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
12774	Hill Haven Dr.	11700	11	131.01	770	26	0.38	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
35662	Hillcrest Pkwy. (E)	13100	12	136.10	115	26	0.06	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
35663	Hillcrest Pkwy. (E)	13200	11	136.10	480	26	0.24	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
12901	Hillside Dr.	4000	9	80.00	330	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
12902	Hillside Dr.	4100	9	80.00	465	36	0.32	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
12947	Hobson Av. (E)	100	6	56.00	340	36	0.23	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
12948	Hobson Av. (E)	200	6	56.00	380	36	0.26	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
13007	Holcomb Rd.	1300	5	92.01	479	36	0.33	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13008	Holcomb Rd.	1400	5	92.01	805	36	0.55	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13009	Holcomb Rd.	1500	5	92.01	490	36	0.33	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13010	Holcomb Rd.	1600	5	92.01	330	36	0.23	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13011	Holcomb Rd.	1700	5	92.01	1,159	36	0.79	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13152	Homeplace Dr.	9900	8	118.00	401	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
13153	Homeplace Dr.	10000	8	118.00	439	26	0.22	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
13154	Homeplace Dr.	10100	8	118.00	390	26	0.19	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
13163	Homer St.	3200	9	3.00	378	26	0.19	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
13164	Homer St.	3300	9	3.00	335	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
13165	Homer St.	3400	9	3.00	303	26	0.15	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
13204	Hope St.	1600	14	11.01	350	26	0.17	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
36776	Houston St. (N)	1900	2	21.00	356	42	0.28	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36777	Houston St. (N)	2000	2	21.00	356	42	0.28	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36778	Houston St. (N)	2100	2	21.00	316	42	0.25	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
35487	Houston St. (N)	2200	2	19.00	250	46	0.22	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36779	Houston St. (N)	2300	2	19.00	636	46	0.55	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36781	Houston St. (N)	2500	2	19.00	589	46	0.51	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36782	Houston St. (N)	2600	2	19.00	231	46	0.20	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36783	Houston St. (N)	2700	2	19.00	986	46	0.86	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36784	Houston St. (N)	2800	2	19.00	1,108	46	0.97	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36785	Houston St. (N)	2900	2	19.00	542	44	0.45	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36722	Howard Payne Dr.	800	8	112.00	419	32	0.25	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
13300	Howell St.	2400	14	18.00	223	30	0.13	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
13305	Howell St.	3400	14	17.02	600	30	0.34	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
13344	Hudspeth Av.	1200	4	59.01	307	26	0.15	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
13345	Hudspeth Av.	1300	4	57.00	470	26	0.23	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
13346	Hudspeth Av.	1400	4	57.00	564	26	0.28	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
13347	Hudspeth Av.	1500	4	57.00	480	26	0.24	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
13348	Hudspeth Av.	1600	4	57.00	748	26	0.37	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
13349	Hudspeth Av.	1700	4	57.00	539	26	0.27	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
35488	Hughes La.	13000	11	136.08	780	36	0.53	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
13372	Hughes La.	13100	11	136.08	420	36	0.29	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
13373	Hughes La.	13200	11	136.08	420	36	0.29	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
13374	Hughes La.	13300	11	136.08	325	36	0.22	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
13375	Hughes La.	13400	11	136.08	390	36	0.27	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
13376	Hughes La.	13500	11	136.08	220	36	0.15	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
13377	Hughes La.	13600	11	136.08	220	36	0.15	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
13378	Hughes La.	13700	11	136.08	765	36	0.52	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
13379	Hughes La.	13800	11	136.08	437	36	0.30	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
13422	Hunnicut Rd.	8000	7	122.04	490	26	0.24	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
13423	Hunnicut Rd.	8100	7	122.04	1,262	26	0.62	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
36867	Hunters Bend La.	5500	3	165.10	418	36	0.29	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
13441	Hunters View La.	5800	4	110.02	155	26	0.08	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
13442	Hunters View La.	5900	4	110.02	841	26	0.41	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
13448	Huntingdon Av.	2100	6	89.00	344	36	0.23	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
13449	Huntingdon Av.	2200	6	89.00	332	36	0.23	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002

Street History Improvements 1999-2002

13510	Idaho Av.	4000	4	59.01	364	36	0.25	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
13511	Idaho Av.	4100	4	59.01	478	36	0.33	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
13512	Idaho Av.	4200	4	59.01	889	26	0.44	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
33189	Ikel Dr.	17200	12	136.18	487	26	0.24	Asphalt	1981	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
13750	Inwood Rd.	3500	14	71.02	670	66	0.84	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13751	Inwood Rd.	3600	14	71.02	287	66	0.36	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13752	Inwood Rd.	3700	14	71.02	342	66	0.43	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13753	Inwood Rd.	3800	14	71.02	342	66	0.43	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13754	Inwood Rd.	3900	14	71.02	508	66	0.64	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13755	Inwood Rd.	4000	14	71.02	372	66	0.47	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13756	Inwood Rd.	4100	14	71.02	310	66	0.39	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13820	Iowa Av. (E)	1300	6	55.00	298	30	0.17	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
13821	Iowa Av. (E)	1400	6	55.00	298	30	0.17	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
13853	Irving Blvd.	1600	6	100.00	689	66	0.86	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13854	Irving Blvd.	1700	6	100.00	539	66	0.67	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13855	Irving Blvd.	1800	6	100.00	668	66	0.84	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13856	Irving Blvd.	1900	6	100.00	500	66	0.63	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13857	Irving Blvd.	2000	6	100.00	790	66	0.99	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13858	Irving Blvd.	2100	6	100.00	716	66	0.90	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13859	Irving Blvd.	2200	6	100.00	1,135	66	1.42	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13860	Irving Blvd.	2300	6	100.00	850	66	1.06	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
13861	Irving Blvd.	2400	6	100.00	850	66	1.06	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
33204	J J Lemmon Rd.	6800	8	114.02	2,595	46	2.26	Concrete	2001	1976	2001	Construction	Construction	Construction	Construction	2001
13937	J J Lemmon Rd.	6900	8	167.02	1,033	46	0.90	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
34815	J J Lemmon Rd.	7000	8	167.02	315	46	0.27	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
13955	Jacobie Blvd.	7500	5	93.01	251	26	0.12	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
13956	Jacobie Blvd.	7600	5	93.01	531	26	0.26	Asphalt	1960	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
13957	Jacobie Blvd.	7700	5	93.01	500	26	0.25	Asphalt	1960	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
13958	Jacobie Blvd.	7800	5	93.01	585	26	0.29	Asphalt	1960	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
13959	Jacobie Blvd.	7900	5	93.01	645	26	0.32	Asphalt	1960	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
13960	Jacobie Blvd.	8000	5	93.01	371	26	0.18	Asphalt	1960	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
14034	Jared Dr.	9000	8	117.00	547	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
14040	Jason Dr.	4700	9	79.05	552	36	0.38	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
14059	Jefferson Blvd. (E)	1000	1	20.00	380	57	0.41	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
14066	Jefferson Blvd. (W)	200	1	47.00	568	58	0.62	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
14145	Jennie Lee La.	9200	4	120.00	621	40	0.47	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
14146	Jennie Lee La.	9300	4	120.00	710	40	0.54	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
14147	Jennie Lee La.	9600	5	120.00	770	40	0.58	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
14148	Jennie Lee La.	9700	5	120.00	180	40	0.14	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
14153	Jeran Dr.	700	5	92.02	469	26	0.23	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
14154	Jeran Dr.	800	5	92.02	443	26	0.22	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
14273	Joe Field Rd.	2400	6	99.00	1,051	36	0.72	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
14274	Joe Field Rd.	2500	6	99.00	1,064	36	0.73	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
14275	Joe Field Rd.	2600	2	99.00	850	36	0.58	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
36546	John McCoy Dr.	2300	4	91.01	820	26	0.40	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
14295	Jonelle Av.	500	5	93.03	834	26	0.41	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
14296	Jonelle Av.	600	5	93.03	839	26	0.41	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
14297	Jonelle Av.	700	5	93.03	953	26	0.47	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
36828	Jubilant Dr.	7700	8	109.00	335	32	0.20	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
36829	Jubilant Dr.	7800	8	109.00	607	32	0.37	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
36830	Jubilant Dr.	7900	8	109.00	774	32	0.47	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
33969	Judi St.	7000	12	317.98	900	26	0.44	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
14458	Justin Av. (N)	1000	3	107.01	535	18	0.18	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
14459	Justin Av. (N)	1100	3	107.01	760	18	0.26	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
14460	Justin Av. (N)	1200	3	107.01	734	18	0.25	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
14588	Kenway La.	4200	4	60.02	292	26	0.14	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
14649	Kiest Blvd. (E)	300	4	59.02	750	60	0.85	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
14650	Kiest Blvd. (E)	400	4	59.02	367	60	0.42	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002

Street History Improvements 1999-2002

14651	Kiest Blvd. (E)	500	4	59.02	366	60	0.42	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
14652	Kiest Blvd. (E)	600	4	59.02	395	60	0.45	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
14653	Kiest Blvd. (E)	700	4	59.01	350	60	0.40	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
14654	Kiest Blvd. (E)	800	4	59.01	371	60	0.42	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
14655	Kiest Blvd. (E)	900	4	59.01	400	60	0.45	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
14656	Kiest Blvd. (E)	1000	4	59.01	436	60	0.50	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
14657	Kiest Blvd. (E)	1100	4	59.01	672	60	0.76	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
14658	Kiest Blvd. (E)	1200	4	57.00	655	60	0.74	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
14659	Kiest Blvd. (E)	1300	4	57.00	628	60	0.71	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
14660	Kiest Blvd. (E)	1400	4	57.00	530	60	0.60	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
14686	Kiest Blvd. (W)	100	6	56.00	950	60	1.08	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
14687	Kiest Blvd. (W)	200	6	56.00	469	60	0.53	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
14688	Kiest Blvd. (W)	300	4	60.02	789	60	0.90	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
14689	Kiest Blvd. (W)	400	4	60.02	462	60	0.53	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
14690	Kiest Blvd. (W)	500	6	60.01	745	60	0.85	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
14691	Kiest Blvd. (W)	600	6	60.01	362	60	0.41	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
14748	Kiest Blvd. (W)	6400	3	165.01	350	60	0.40	Asphalt		1999	1999	Other Project	Resurfacing	Other Project	Other Project	1999
14749	Kiest Blvd. (W)	6500	3	165.01	350	60	0.40	Asphalt		1999	1999	Other Project	Resurfacing	Other Project	Other Project	1999
14756	Kiest Blvd. (W)	7200	3	165.01	390	60	0.44	Asphalt		1999	1999	Other Project	Resurfacing	Other Project	Other Project	1999
14758	Kiest Blvd. (W)	7400	3	165.01	390	60	0.44	Asphalt		1999	1999	Other Project	Resurfacing	Other Project	Other Project	1999
14759	Kiest Blvd. (W)	7500	3	165.01	390	60	0.44	Asphalt		1999	1999	Other Project	Resurfacing	Other Project	Other Project	1999
35925	Kiest Blvd. (W)	7600	3	165.01	390	60	0.44	Asphalt		1999	1999	Other Project	Resurfacing	Other Project	Other Project	1999
14772	Kiest Valley Pkwy.	3700	3	108.02	1,060	26	0.52	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
14773	Kiest Valley Pkwy.	3800	3	108.02	470	26	0.23	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
14774	Kiest Valley Pkwy.	3900	3	108.02	1,305	26	0.64	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
14828	King Arthur Dr.	9100	6	100.00	1,066	36	0.45	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
36728	Kingfisher Dr.	4500	3	165.01	433	33	0.27	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36729	Kingfisher Dr.	4600	3	165.01	674	33	0.42	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
14856	Kings Rd.	2600	2	4.04	276	28	0.15	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
14857	Kings Rd.	2700	2	4.04	273	28	0.14	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
14858	Kings Rd.	2800	2	4.04	575	28	0.30	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
34830	Kingscrest Cir.	15600	12	136.05	660	26	0.33	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
33978	Kingscrest Cir.	15700	12	136.05	670	26	0.33	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
14926	Kingswood Dr.	2300	7	122.04	1,015	26	0.50	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
32445	Kirkham Dr.	7300	12	317.98	710	26	0.35	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
36831	Kirkland Ct.	7700	8	109.00	497	26	0.24	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
36832	Kirkland Ct.	7800	8	109.00	219	26	0.11	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
15004	Kittyhawk La.	9600	8	118.00	410	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
30940	Kittyhawk La.	9700	8	118.00	575	26	0.28	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
15005	Kittyhawk La.	9900	8	118.00	300	26	0.15	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
15006	Kittyhawk La.	10000	8	118.00	300	26	0.15	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
15007	Kittyhawk La.	10100	8	118.00	445	26	0.22	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
15072	Kodiak Dr.	200	8	117.00	573	26	0.28	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
15085	Komalty Dr.	7700	8	116.01	512	36	0.35	Asphalt	1959	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15086	Komalty Dr.	7800	8	116.01	395	36	0.27	Asphalt	1959	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15087	Komalty Dr.	7900	8	116.01	630	26	0.31	Asphalt	1959	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15088	Komalty Dr.	8000	8	116.01	610	26	0.30	Asphalt	1959	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15173	La Grange Dr.	6400	8	167.01	1,220	26	0.60	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
15174	La Grange Dr.	6500	8	167.01	607	26	0.30	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
15175	La Grange Dr.	6600	8	167.01	330	26	0.16	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
15176	La Grange Dr.	6700	8	167.01	585	26	0.29	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
15223	La Sobrina Dr.	7100	12	136.05	430	26	0.21	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
15224	La Sobrina Dr.	7200	12	136.05	709	26	0.35	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
15225	La Sobrina Dr.	7300	12	136.05	520	26	0.26	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
15226	La Sobrina Dr.	7400	12	136.05	575	26	0.28	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
15467	Lakemere Dr.	10000	10	130.04	685	26	0.34	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
15468	Lakemere Dr.	10100	10	130.04	584	36	0.40	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
36787	Lamar St. (N)	2300	2	19.00	235	44	0.20	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001

Street History Improvements 1999-2002

36788	Lamar St. (N)	2400	2	19.00	221	44	0.18	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
15535	Lamar St. (S)	1000	2	33.00	366	60	0.42	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15536	Lamar St. (S)	1100	2	33.00	366	60	0.42	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15537	Lamar St. (S)	1200	2	33.00	366	60	0.42	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15538	Lamar St. (S)	1300	2	33.00	400	60	0.45	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15539	Lamar St. (S)	1400	2	33.00	293	60	0.33	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15540	Lamar St. (S)	1500	2	33.00	293	60	0.33	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15541	Lamar St. (S)	1600	2	33.00	293	60	0.33	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15542	Lamar St. (S)	1700	2	33.00	540	60	0.61	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15543	Lamar St. (S)	1800	2	33.00	400	60	0.45	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15544	Lamar St. (S)	1900	2	33.00	507	60	0.58	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15545	Lamar St. (S)	2000	2	33.00	262	80	0.40	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15546	Lamar St. (S)	2100	2	33.00	262	50	0.25	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15547	Lamar St. (S)	2200	2	33.00	502	50	0.48	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15548	Lamar St. (S)	2300	2	33.00	200	50	0.19	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15549	Lamar St. (S)	2400	2	33.00	200	50	0.19	Asphalt	1950	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15550	Lamar St. (S)	2500	7	34.00	372	46	0.32	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15551	Lamar St. (S)	2600	7	34.00	369	46	0.32	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15552	Lamar St. (S)	2700	7	34.00	436	46	0.38	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15553	Lamar St. (S)	2800	7	34.00	487	50	0.46	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15554	Lamar St. (S)	2900	7	34.00	484	46	0.42	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15555	Lamar St. (S)	3000	7	34.00	510	46	0.44	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15556	Lamar St. (S)	3100	7	34.00	286	46	0.25	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15557	Lamar St. (S)	3200	7	34.00	366	46	0.32	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15558	Lamar St. (S)	3300	7	34.00	349	46	0.30	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15559	Lamar St. (S)	3400	7	34.00	187	46	0.16	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15560	Lamar St. (S)	3500	7	34.00	332	46	0.29	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15561	Lamar St. (S)	3600	7	40.00	951	55	0.99	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15562	Lamar St. (S)	3700	7	40.00	368	55	0.38	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15563	Lamar St. (S)	3800	7	40.00	325	55	0.34	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15564	Lamar St. (S)	3900	7	40.00	325	55	0.34	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15565	Lamar St. (S)	4000	7	40.00	325	55	0.34	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15566	Lamar St. (S)	4100	7	40.00	675	55	0.70	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
15712	Langdale Cir.	8600	10	130.07	906	26	0.45	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
36549	Lanyon Dr.	7000	4	122.02	610	36	0.42	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
36550	Lanyon Dr.	7100	4	122.02	1,020	36	0.70	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
36553	Larkin Dr.	7000	4	122.02	110	36	0.08	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
36554	Larkin Dr.	7100	4	122.02	880	36	0.60	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
36699	Las Villas Av.	2600	3	108.01	500	36	0.34	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36700	Las Villas Av.	2700	3	108.01	358	36	0.24	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
32451	Lattimore Dr.	7000	12	317.98	800	26	0.39	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
15950	Lavendale Av.	7300	11	131.01	326	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
15951	Lavendale Av.	7400	11	131.01	334	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
15952	Lavendale Av.	7500	11	131.01	334	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
15953	Lavendale Av.	7600	11	131.01	214	26	0.11	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
15980	Lawnview Av.	4100	7	83.00	865	40	0.66	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
15981	Lawnview Av.	4200	7	83.00	390	40	0.30	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
15982	Lawnview Av.	4300	7	83.00	560	40	0.42	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
15983	Lawnview Av.	4400	7	83.00	629	40	0.48	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
36868	Laysan Ct.	5500	3	165.10	403	36	0.27	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
33588	Leavally Cir.	15500	12	136.07	812	26	0.40	Asphalt	1967	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
16288	Lemmon Av.	2500	14	16.00	420	60	0.48	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
16289	Lemmon Av.	2600	14	7.01	324	66	0.41	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
16289	Lemmon Av.	2600	14	7.01	324	66	0.41	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
16293	Lemmon Av.	3000	14	7.01	221	40	0.17	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
16294	Lemmon Av.	3100	14	7.01	653	40	0.49	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
16295	Lemmon Av.	3200	14	7.01	375	40	0.28	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
16296	Lemmon Av.	3300	14	7.01	269	40	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000

Street History Improvements 1999-2002

16297	Lemmon Av.	3400	14	6.04	350	40	0.27	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
16298	Lemmon Av.	3500	14	6.04	260	66	0.33	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
16464	Liberty St.	900	14	16.00	325	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
16465	Liberty St.	1000	14	16.00	368	26	0.18	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
16475	Lil Green St.	2000	7	25.00	325	26	0.16	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
16483	Limestone Dr.	9600	5	119.00	1,075	26	0.53	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
16484	Limestone Dr.	9700	5	119.00	488	26	0.24	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
16512	Linden La.	6300	11	132.00	375	26	0.18	Asphalt	1953	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
16513	Linden La.	6400	11	132.00	564	26	0.28	Asphalt	1953	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
16514	Linden La.	6500	11	132.00	628	26	0.31	Asphalt	1953	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
16596	Lippitt Av.	10300	9	82.00	597	26	0.29	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
16597	Lippitt Av.	10400	9	82.00	1,081	26	0.53	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
16610	Lippitt Av.	11700	9	128.00	510	26	0.25	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
16611	Lippitt Av.	11800	9	128.00	500	26	0.25	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
16628	Live Oak St.	2100	14	21.00	350	50	0.33	Asphalt	1978	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
36556	Livvie Meador La.	7600	4	91.01	614	26	0.30	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
16726	Lloyd Valley La.	6900	11	131.01	520	26	0.26	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
16737	Locarno Dr.	9100	10	78.12	896	26	0.44	Asphalt	1971	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
16738	Locarno Dr.	9200	10	78.12	685	26	0.34	Asphalt	1971	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
16739	Locarno Dr.	9300	10	78.12	660	26	0.33	Asphalt	1971	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
16837	Lombardy La.	2500	6	99.00	1,422	36	0.97	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
16838	Lombardy La.	2600	6	99.00	2,625	36	1.79	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
16850	Lomo Alto Dr.	8000	13	73.01	422	26	0.21	Asphalt		1999	1999	Other Project	Resurfacing	Other Project	Other Project	1999
16851	Lomo Alto Dr.	8100	13	73.01	473	26	0.23	Asphalt		1999	1999	Other Project	Resurfacing	Other Project	Other Project	1999
16852	Lomo Alto Dr.	8200	13	73.01	457	26	0.23	Asphalt		1999	1999	Other Project	Resurfacing	Other Project	Other Project	1999
16890	Longview St.	5400	9	3.00	813	26	0.40	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
16891	Longview St.	5500	9	3.00	712	30	0.40	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
16893	Longvista Dr.	15900	12	136.05	652	26	0.32	Asphalt	1971	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
16894	Longvista Dr.	16000	12	136.05	1,463	26	0.72	Asphalt	1971	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
16895	Longvista Dr.	16100	12	136.05	559	26	0.28	Asphalt	1972	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
17011	Love Field Dr.	3400	14	4.03	154	40	0.12	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
17055	Lovett Av.	6300	7	84.00	456	26	0.22	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
17056	Lovett Av.	6400	7	84.00	360	26	0.18	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
17057	Lovett Av.	6500	7	84.00	295	26	0.15	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
17058	Lovett Av.	6600	7	84.00	295	26	0.15	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
17059	Lovett Av.	6700	7	84.00	490	26	0.24	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
31409	Lucas Dr.	2100	2	4.01	210	36	0.14	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
17099	Lucas Dr.	2200	2	4.01	405	36	0.28	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
17101	Lucas Dr.	2400	2	4.01	702	26	0.35	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
36561	Lucile Herrin La.	2700	4	91.01	611	26	0.30	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
17122	Lucy St.	6500	5	93.03	344	26	0.17	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
17204	Lynworth Dr.	7400	12	136.07	691	26	0.34	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
17231	Macomba Ct.	9500	5	118.00	320	26	0.16	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17241	Maddox Av.	8300	5	92.02	623	26	0.31	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17242	Maddox Av.	8400	5	92.02	665	26	0.33	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17274	Madras Dr.	8300	5	92.02	425	26	0.21	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
17436	Malcolm X Blvd. (S)	5200	7	39.01	300	26	0.15	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17437	Malcolm X Blvd. (S)	5300	7	39.01	430	26	0.21	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
36866	Mandarin Wy.	5500	3	165.10	1,005	36	0.69	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
17503	Manor Wy.	2800	2	4.03	352	36	0.24	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
17504	Manor Wy.	2900	2	4.03	352	36	0.24	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
17505	Manor Wy.	3000	2	4.03	352	36	0.24	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
17539	Maple Av.	3800	2	5.00	369	60	0.42	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
36696	Mariano Plz.	1400	3	107.02	219	36	0.15	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
17710	Market Center Blvd.	2200	6	100.00	279	66	0.35	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
17726	Markville Dr.	9100	10	78.10	690	40	0.52	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
17727	Markville Dr.	9200	10	78.10	890	40	0.67	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
17744	Marlborough Av. (S)	1200	1	53.00	620	30	0.35	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999

Street History Improvements 1999-2002

17758	Marquita Av.	5700	14	2.02	628	26	0.31	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
17759	Marquita Av.	5800	14	2.02	662	26	0.33	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
17760	Marquita Av.	5900	14	2.02	652	26	0.32	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
17761	Marquita Av.	6000	14	2.02	616	26	0.30	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
17783	Marsalis Av. (S)	1000	6	54.00	1,000	60	1.14	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17784	Marsalis Av. (S)	1100	6	54.00	655	60	0.74	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17785	Marsalis Av. (S)	1200	6	54.00	600	60	0.68	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17786	Marsalis Av. (S)	1300	6	54.00	665	60	0.76	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17787	Marsalis Av. (S)	1400	6	54.00	681	60	0.77	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17788	Marsalis Av. (S)	1500	6	54.00	337	60	0.38	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17789	Marsalis Av. (S)	1600	6	54.00	336	60	0.38	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17790	Marsalis Av. (S)	1700	6	54.00	508	60	0.58	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17791	Marsalis Av. (S)	1800	6	54.00	451	60	0.51	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17792	Marsalis Av. (S)	1900	6	54.00	410	60	0.47	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17793	Marsalis Av. (S)	2000	6	54.00	432	60	0.49	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17794	Marsalis Av. (S)	2100	6	54.00	496	60	0.56	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17795	Marsalis Av. (S)	2200	6	54.00	400	60	0.45	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
17842	Marsh La.	10000	13	97.02	700	66	0.88	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
17843	Marsh La.	10100	13	97.02	900	66	1.13	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
17844	Marsh La.	10200	13	97.02	400	66	0.50	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
17845	Marsh La.	10300	13	97.02	583	66	0.73	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
17846	Marsh La.	10400	13	97.02	610	66	0.76	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
17847	Marsh La.	10500	13	97.02	800	66	1.00	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
17848	Marsh La.	10600	13	97.02	600	66	0.75	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
17849	Marsh La.	10700	13	97.02	650	66	0.81	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
17857	Marsh La.	11500	13	96.07	435	66	0.54	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
17858	Marsh La.	11600	13	96.07	435	66	0.54	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
17859	Marsh La.	11700	13	96.07	669	66	0.84	Concrete	2002	2002	Construction	Construction	Construction	Construction	Construction	2002
17880	Martin Luther King Blvd.	1500	7	34.00	378	66	0.47	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17881	Martin Luther King Blvd.	1600	7	34.00	636	66	0.80	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17882	Martin Luther King Blvd.	1700	7	34.00	364	66	0.46	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17883	Martin Luther King Blvd.	1800	7	34.00	364	66	0.46	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17884	Martin Luther King Blvd.	1900	7	34.00	330	66	0.41	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17885	Martin Luther King Blvd.	2300	7	35.00	300	66	0.38	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17886	Martin Luther King Blvd.	2400	7	35.00	504	66	0.63	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17887	Martin Luther King Blvd.	2500	7	35.00	510	66	0.64	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17888	Martin Luther King Blvd.	2600	7	35.00	503	66	0.63	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17889	Martin Luther King Blvd.	2700	7	35.00	497	66	0.62	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17890	Martin Luther King Blvd.	2800	7	35.00	546	66	0.68	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17891	Martin Luther King Blvd.	2900	7	35.00	521	66	0.65	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17892	Martin Luther King Blvd.	3000	7	35.00	550	66	0.69	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17893	Martin Luther King Blvd.	3100	7	35.00	500	66	0.63	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17894	Martin Luther King Blvd.	3200	7	28.00	450	66	0.56	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17895	Martin Luther King Blvd.	3300	7	28.00	220	66	0.28	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
17946	Mary St.	1500	14	11.01	180	26	0.09	Concrete	1999	1999	Construction	Construction	Construction	Construction	Construction	1999
17967	Maryland Av.	2800	6	56.00	650	26	0.32	Concrete	2000	2000	Construction	Construction	Construction	Construction	Construction	2000
17968	Maryland Av.	2900	6	56.00	620	26	0.31	Concrete	2000	2000	Construction	Construction	Construction	Construction	Construction	2000
17991	Mason Dells Dr.	7000	11	131.01	735	26	0.36	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
17994	Mason Dells Dr.	7300	11	131.01	220	26	0.11	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
17995	Mason Dells Dr.	7400	11	131.01	365	26	0.18	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
17996	Mason Dells Dr.	7500	11	131.01	720	26	0.35	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
31410	Mason Dells Dr.	7700	11	131.01	470	26	0.23	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
33248	Mason Dells Dr.	7800	11	131.01	425	26	0.21	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
36567	Max Goldblatt Dr.	2600	4	91.01	749	26	0.37	Concrete	1999	1999	Construction	Construction	Construction	Construction	Construction	1999
18288	Mckinney Av.	1600	14	19.00	371	40	0.28	Asphalt	1969	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
18289	Mckinney Av.	1700	14	19.00	100	40	0.08	Asphalt	1969	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
18290	Mckinney Av.	1800	14	19.00	187	40	0.14	Asphalt	1969	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
18294	Mckinney Av.	2200	14	18.00	326	40	0.25	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001

Street History Improvements 1999-2002

18295	Mckinney Av.	2300	14	18.00	250	40	0.19	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
18296	Mckinney Av.	2400	14	18.00	198	40	0.15	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
18297	Mckinney Av.	2500	14	18.00	440	40	0.33	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
18298	Mckinney Av.	2600	14	18.00	422	40	0.32	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
18299	Mckinney Av.	2700	14	18.00	386	40	0.29	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
18300	Mckinney Av.	2800	14	18.00	450	40	0.34	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
18301	Mckinney Av.	2900	14	18.00	426	66	0.53	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
18310	Mckinney Av.	3800	14	7.01	330	36	0.23	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
18311	Mckinney Av.	3900	14	7.01	962	36	0.66	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
18312	Mckinney Av.	4000	14	7.01	853	36	0.58	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
18313	Mckinney Av.	4100	14	7.01	815	36	0.56	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
31419	Mckinney Av.	4200	14	7.02	610	36	0.42	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
31420	Mckinney Av.	4300	14	7.02	650	36	0.44	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
31421	Mckinney Av.	4400	14	7.02	650	36	0.44	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
31422	Mckinney Av.	4500	14	7.02	635	36	0.43	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
31423	Mckinney Av.	4600	14	7.02	740	36	0.50	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
31424	Mckinney Av.	4700	14	7.02	450	36	0.31	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
31425	Mckinney Av.	4800	14	7.02	450	36	0.31	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
18318	Mckinnon St.	2700	2	19.00	519	66	0.65	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
18338	McLarty Dr.	3700	8	167.01	645	26	0.32	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
18385	Mcvey Av. (E)	100	6	56.00	350	26	0.17	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
32457	McVey Av. (W)	100	6	56.00	525	36	0.36	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
18438	Meadow Oaks Dr.	7300	11	131.02	680	26	0.33	Asphalt	1969	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
18439	Meadow Oaks Dr.	7400	11	131.02	480	26	0.24	Asphalt	1969	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
18479	Meadow St.	3400	7	37.00	290	26	0.14	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
18410	Meadowknoll Cir.	9000	10	78.13	173	26	0.09	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
18424	Meadowknoll Dr.	9100	10	78.13	275	40	0.21	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
18496	Meadowvista Dr.	15800	12	136.05	397	26	0.20	Asphalt	1969	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
18620	Mediterranean Cir. (S)	8500	10	130.07	212	26	0.10	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
18760	Merrell Rd.	2800	6	97.01	1,500	44	1.25	Asphalt	1964	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
18761	Merrell Rd.	2900	6	97.01	1,370	36	0.93	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
18821	Merriman Pkwy.	7200	10	78.12	410	36	0.28	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
18822	Merriman Pkwy.	7300	10	78.12	410	36	0.28	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
18823	Merriman Pkwy.	7400	10	78.12	400	36	0.27	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
18824	Merriman Pkwy.	7500	10	78.12	400	36	0.27	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
18825	Merriman Pkwy.	7600	10	78.12	400	36	0.27	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
18826	Merriman Pkwy.	7700	10	78.12	400	36	0.27	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
18827	Merriman Pkwy.	7800	10	78.12	400	36	0.27	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
36064	Merrivood Dr.	7500	10	78.14	575	36	0.39	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
18857	Metropolitan Av.	2900	7	37.00	552	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
18858	Metropolitan Av.	3000	7	37.00	232	26	0.11	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
18859	Metropolitan Av.	3100	7	37.00	602	26	0.30	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
18860	Metropolitan Av.	3200	7	27.02	279	26	0.14	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
18861	Metropolitan Av.	3300	7	27.02	190	26	0.09	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
18888	Meyers St.	2400	7	29.00	424	30	0.24	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
18889	Meyers St.	2500	7	29.00	410	30	0.23	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
18890	Meyers St.	2600	7	29.00	756	30	0.43	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
18893	Meyers St.	2900	7	35.00	400	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
18894	Meyers St.	3000	7	36.00	370	36	0.25	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
18895	Meyers St.	3100	7	36.00	315	36	0.21	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
18922	Michigan Av.	1200	6	54.00	789	26	0.39	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
18934	Michigan Av.	2400	6	56.00	430	30	0.24	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
18935	Michigan Av.	2500	6	56.00	381	30	0.22	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
18958	Midbury Dr.	7800	11	131.01	560	26	0.28	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
18969	Middle Downs Dr.	8800	10	78.13	505	26	0.25	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
18980	Midpark Rd.	8300	11	192.09	500	36	0.34	Asphalt	1972	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
35680	Midpark Rd.	8400	11	192.09	350	36	0.24	Asphalt	1972	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
19123	Military Pkwy. Serv. N	6800	7	84.00	495	36	0.34	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999

Street History Improvements 1999-2002

19124	Military Pkwy. Serv. N	6900	7	84.00	480	36	0.33	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
19151	Mill Hollow Dr.	9200	10	78.10	155	26	0.08	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
19152	Mill Hollow Dr.	9300	10	78.10	450	26	0.22	Asphalt	1973	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
19153	Mill Hollow Dr.	9400	10	78.10	290	26	0.14	Asphalt	1973	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
19154	Mill Hollow Dr.	9500	10	78.10	312	26	0.15	Asphalt	1973	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
19155	Mill Hollow Dr.	9600	10	78.10	430	26	0.21	Asphalt	1973	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
19166	Mill Valley La.	9700	8	117.00	552	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
19167	Mill Valley La.	9800	8	117.00	530	26	0.26	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
19301	Missouri Av. (E)	600	6	56.00	337	30	0.19	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
32473	Missy Dr.	6400	12	317.98	450	26	0.22	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
32474	Missy Dr.	6500	12	317.98	410	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
32475	Missy Dr.	6600	12	317.98	790	26	0.39	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19323	Misty Wood Dr.	6100	5	93.04	603	26	0.30	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
19324	Misty Wood Dr.	6200	5	93.04	350	26	0.17	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
19327	Mitscher Dr.	100	6	56.00	616	26	0.30	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
19328	Mitscher Dr.	200	6	56.00	390	26	0.19	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
19347	Mockingbird La. (E)	5500	9	3.00	493	60	0.56	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19348	Mockingbird La. (E)	5600	9	3.00	613	60	0.70	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19349	Mockingbird La. (E)	5700	14	2.02	650	60	0.74	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19350	Mockingbird La. (E)	5800	14	2.02	750	60	0.85	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19351	Mockingbird La. (E)	5900	14	2.02	630	60	0.72	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19352	Mockingbird La. (E)	6000	14	2.02	600	60	0.68	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19353	Mockingbird La. (E)	6100	14	2.01	975	60	1.11	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19354	Mockingbird La. (E)	6200	14	2.01	956	60	1.09	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19355	Mockingbird La. (E)	6300	14	2.01	690	60	0.78	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19386	Mockingbird La. (W)	1400	6	100.00	500	66	0.63	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
19387	Mockingbird La. (W)	1500	6	100.00	1,100	66	1.38	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
19388	Mockingbird La. (W)	1600	6	100.00	500	66	0.63	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
19389	Mockingbird La. (W)	1700	6	100.00	500	66	0.63	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
19390	Mockingbird La. (W)	1800	6	100.00	1,043	66	1.30	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
19391	Mockingbird La. (W)	1900	6	100.00	469	66	0.59	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
19392	Mockingbird La. (W)	2000	2	4.03	564	66	0.71	Asphalt		2002	2002	2002 City Wide	Resurfacing	FAUS	City Wide	2002
19415	Mockingbird La. (W)	4300	14	71.02	275	66	0.34	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
19416	Mockingbird La. (W)	4400	14	71.02	166	66	0.21	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
19417	Mockingbird La. (W)	4500	14	71.02	296	66	0.37	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
19418	Mockingbird La. (W)	4600	14	71.02	297	66	0.37	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
19419	Mockingbird La. (W)	4700	14	71.02	347	66	0.43	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
19420	Mockingbird La. (W)	4800	14	71.02	260	66	0.33	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
19421	Mockingbird La. (W)	4900	14	71.02	231	66	0.29	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
19422	Mockingbird La. (W)	5000	14	71.02	370	66	0.46	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
19423	Mockingbird La. (W)	5100	14	71.02	350	66	0.44	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
19424	Mockingbird La. (W)	5200	14	71.02	360	66	0.45	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
19425	Mockingbird La. (W)	5300	14	71.01	800	40	0.61	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
19429	Modella Av.	2900	6	96.06	980	36	0.67	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
19450	Mohawk Dr.	7000	2	4.03	273	36	0.19	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
19451	Mohawk Dr.	7100	2	4.03	274	36	0.19	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
19452	Mohawk Dr.	7200	2	4.03	341	36	0.23	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
19453	Mohawk Dr.	7300	2	4.03	406	36	0.28	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
19454	Mohawk Dr.	7400	2	4.03	340	36	0.23	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
19455	Mohawk Dr.	7500	2	4.03	373	26	0.18	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
19456	Mohawk Dr.	7600	2	4.03	130	26	0.06	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
19457	Mohawk Dr.	7700	2	4.03	175	26	0.09	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
19458	Mohawk Dr.	7800	2	4.03	321	26	0.16	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
19459	Mohawk Dr.	7900	2	4.03	319	26	0.16	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
19460	Mohawk Dr.	8000	2	4.03	369	26	0.18	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
19621	Monticello Av.	3000	14	7.02	330	30	0.19	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19622	Monticello Av.	3100	14	7.02	419	30	0.24	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19635	Monticello Av.	6300	14	2.01	932	26	0.46	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001

Street History Improvements 1999-2002

19683	Moonhill Dr.	6500	8	167.01	232	26	0.11	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
19722	Morning Frost Trl.	3900	4	60.02	401	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
19744	Morocco Av. (N)	600	3	107.01	241	36	0.16	Concrete	1999	1999	1999	Construction	Construction	Construction	Construction	1999
19745	Morocco Av. (N)	700	3	107.01	280	36	0.19	Concrete	1999	1999	1999	Construction	Construction	Construction	Construction	1999
19746	Morocco Av. (N)	800	3	107.01	275	36	0.19	Concrete	1999	1999	1999	Construction	Construction	Construction	Construction	1999
19747	Morocco Av. (N)	900	3	107.01	275	36	0.19	Concrete	1999	1999	1999	Construction	Construction	Construction	Construction	1999
19748	Morocco Av. (N)	1000	3	107.01	530	26	0.26	Concrete	1999	1999	1999	Construction	Construction	Construction	Construction	1999
19749	Morocco Av. (N)	1100	3	107.01	760	26	0.37	Concrete	1999	1999	1999	Construction	Construction	Construction	Construction	1999
31013	Moss Farm La.	9300	10	78.13	640	26	0.32	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
31014	Moss Farm La.	9400	10	78.13	320	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
31015	Moss Farm La.	9500	10	78.13	445	26	0.22	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
31016	Moss Farm La.	9600	10	78.13	460	26	0.23	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
31438	Mosscove Cir.	15500	12	136.07	822	26	0.40	Asphalt	1967	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
19823	Mossglen Dr.	2500	5	120.00	1,277	26	0.63	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
19824	Mossglen Dr.	2600	5	120.00	265	26	0.13	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
19825	Mossglen Dr.	2700	5	120.00	619	26	0.30	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
34062	Mumford Ct.	7100	12	317.98	413	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19963	Munger Av.	3400	14	16.00	180	26	0.09	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19964	Munger Av.	3500	14	16.00	317	26	0.16	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19965	Munger Av.	3600	14	16.00	308	26	0.15	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
19966	Munger Av.	3700	14	16.00	284	26	0.14	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
20007	Murdeaux La. (N)	100	5	93.04	550	30	0.31	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
20008	Murdeaux La. (N)	200	5	93.04	537	30	0.31	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
20009	Murdeaux La. (N)	300	5	93.04	505	30	0.29	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
20010	Murdeaux La. (N)	400	5	93.04	405	30	0.23	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
20058	Myrtle Springs Av.	2600	6	99.00	2,500	36	1.70	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
20095	Nachita Dr. (S)	100	8	117.00	1,148	22	0.19	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
20096	Nachita Dr. (S)	200	8	117.00	320	26	0.16	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
20097	Nachita Dr. (S)	300	8	117.00	1,264	26	0.62	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
34075	Nicki St.	7000	12	317.98	775	26	0.38	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
20317	Nisqually St.	8300	5	92.02	630	26	0.31	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
20318	Nisqually St.	8400	5	92.02	675	26	0.33	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
20430	North Shore Dr.	100	6	54.00	569	22	0.24	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
20431	North Shore Dr.	200	6	54.00	500	22	0.21	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
20415	Northlake Dr.	500	9	129.00	899	26	0.44	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
20416	Northlake Dr.	600	9	129.00	713	26	0.35	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
34904	Northwest Hwy. (E)	5600	13	78.06	1,000	88	1.67	Concrete	1999	1999	1999	Construction	Construction	Construction	Construction	1999
20623	Northwest Hwy. (W)	6800	13	78.01	325	66	0.41	Asphalt		1999	1999	State	Resurfacing	Other Project	State	1999
20624	Northwest Hwy. (W)	6900	13	78.01	325	60	0.37	Asphalt		1999	1999	State	Resurfacing	Other Project	State	1999
20625	Northwest Hwy. (W)	7000	13	78.01	325	60	0.37	Asphalt		1999	1999	State	Resurfacing	Other Project	State	1999
20626	Northwest Hwy. (W)	7100	13	78.01	325	60	0.37	Asphalt		1999	1999	State	Resurfacing	Other Project	State	1999
20627	Northwest Hwy. (W)	7200	13	78.01	325	60	0.37	Asphalt		1999	1999	State	Resurfacing	Other Project	State	1999
20628	Northwest Hwy. (W)	7300	13	78.01	325	60	0.37	Asphalt		1999	1999	State	Resurfacing	Other Project	State	1999
20629	Northwest Hwy. (W)	7400	13	78.01	600	60	0.68	Asphalt		1999	1999	State	Resurfacing	Other Project	State	1999
20630	Northwest Hwy. (W)	7500	13	78.01	600	60	0.68	Asphalt		1999	1999	State	Resurfacing	Other Project	State	1999
20631	Northwest Hwy. (W)	7600	13	78.01	480	60	0.55	Asphalt		1999	1999	State	Resurfacing	Other Project	State	1999
20632	Northwest Hwy. (W)	7700	13	78.01	480	60	0.55	Asphalt		1999	1999	State	Resurfacing	Other Project	State	1999
20633	Northwest Hwy. (W)	7800	13	78.01	480	60	0.55	Asphalt		1999	1999	State	Resurfacing	Other Project	State	1999
20634	Northwest Hwy. (W)	7900	13	78.01	480	60	0.55	Concrete		1999	1999	State	Resurfacing	Other Project	State	1999
36723	Nuthatch St.	5400	3	165.01	441	33	0.28	Concrete	2001	2001	2001	Construction	Construction	Construction	Construction	2001
36724	Nuthatch St.	5500	3	165.01	441	33	0.28	Concrete	2001	2001	2001	Construction	Construction	Construction	Construction	2001
20785	Oak Grove Av.	3200	14	17.02	411	30	0.23	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
20795	Oak Hill Cir.	1300	5	92.01	450	26	0.22	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
20796	Oak Hill Cir.	1400	5	92.01	865	26	0.43	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
31448	Oak La.	3500	7	28.00	300	26	0.15	Concrete		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
20807	Oak Lawn Av.	1300	6	100.00	432	66	0.54	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20808	Oak Lawn Av.	1400	6	100.00	413	66	0.52	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20809	Oak Lawn Av.	1500	6	100.00	413	66	0.52	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001

Street History Improvements 1999-2002

20810	Oak Lawn Av.	1600	6	100.00	640	66	0.80	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20811	Oak Lawn Av.	1700	6	100.00	300	66	0.38	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20812	Oak Lawn Av.	1800	6	100.00	705	66	0.88	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20813	Oak Lawn Av.	1900	6	100.00	775	66	0.97	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20814	Oak Lawn Av.	2000	2	4.01	362	44	0.30	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20815	Oak Lawn Av.	2100	2	4.01	271	44	0.23	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20816	Oak Lawn Av.	2200	2	5.00	310	60	0.35	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20817	Oak Lawn Av.	2300	2	5.00	312	60	0.35	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20818	Oak Lawn Av.	2400	2	5.00	400	60	0.45	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20819	Oak Lawn Av.	2500	2	5.00	575	60	0.65	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20820	Oak Lawn Av.	2600	2	5.00	349	60	0.40	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20821	Oak Lawn Av.	2700	14	5.00	527	60	0.60	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20822	Oak Lawn Av.	2800	14	5.00	253	60	0.29	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20823	Oak Lawn Av.	2900	14	5.00	408	60	0.46	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
34943	Oak Lawn Av.	3000	14	5.00	300	60	0.34	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20824	Oak Lawn Av.	3100	14	6.04	250	44	0.21	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20825	Oak Lawn Av.	3200	14	6.04	250	44	0.21	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20826	Oak Lawn Av.	3300	14	6.04	456	44	0.38	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20827	Oak Lawn Av.	3400	14	6.04	491	44	0.41	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20828	Oak Lawn Av.	3500	14	6.04	360	44	0.30	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20829	Oak Lawn Av.	3600	14	6.04	399	44	0.33	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20830	Oak Lawn Av.	3700	14	6.04	391	44	0.33	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20831	Oak Lawn Av.	3800	14	6.04	750	44	0.63	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20832	Oak Lawn Av.	3900	14	6.04	424	44	0.35	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20833	Oak Lawn Av.	4000	14	6.03	423	44	0.35	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20834	Oak Lawn Av.	4100	14	6.03	374	44	0.31	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	General Fund	2010	2001
20857	Oak Ridge Dr.	1300	5	92.01	570	26	0.28	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
20858	Oak Ridge Dr.	1400	5	92.01	671	26	0.33	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
35958	Oak Stream	8400	10	78.11	870	36	0.59	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
35959	Oak Stream	8500	10	78.11	275	36	0.19	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
20972	Odeneal St.	500	5	92.02	461	26	0.23	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
20973	Odeneal St.	600	5	92.02	760	26	0.37	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
21000	Ohio Av. (E)	300	6	56.00	760	26	0.37	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
21014	Ohio Av. (W)	100	6	56.00	555	30	0.32	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
21015	Ohio Av. (W)	200	6	56.00	565	30	0.32	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
21016	Ohio Av. (W)	300	6	56.00	196	30	0.11	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
21037	Old Mill Ct.	300	8	117.00	346	26	0.17	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
21040	Old Mill La.	200	8	117.00	983	26	0.48	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
21041	Old Mill La.	300	8	117.00	700	26	0.34	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
21080	Oldbridge Dr.	2300	7	122.04	1,230	26	0.61	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
21140	Opal Av.	3900	4	57.00	249	26	0.12	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
21141	Opal Av.	4000	4	57.00	260	26	0.13	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
21264	Overton Rd. (E)	500	4	59.02	396	44	0.33	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
21265	Overton Rd. (E)	600	4	59.02	365	44	0.30	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
21344	Pacific Av.	1000	2	21.00	185	20	0.07	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
34961	Pacific Av.	2300	14	17.01	200	50	0.19	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
34962	Pacific Av.	2400	14	17.01	468	44	0.39	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
34963	Pacific Av.	2500	14	22.01	610	44	0.51	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
21391	Pagewood Dr.	10700	11	131.03	735	36	0.50	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
21392	Pagewood Dr.	10800	11	131.03	515	36	0.35	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
32845	Park Grove La.	18500	12	317.02	650	26	0.32	Asphalt	1981	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
32846	Park Grove La.	18600	12	317.02	910	26	0.45	Asphalt	1981	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
32847	Park Grove La.	18700	12	317.02	600	26	0.30	Asphalt	1981	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
32848	Park Grove La.	18800	12	317.02	675	26	0.33	Asphalt	1981	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
21546	Park La.	6400	13	77.00	600	26	0.30	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
21547	Park La.	6500	13	77.00	579	26	0.29	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
21548	Park La.	6600	13	77.00	550	26	0.27	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
21549	Park La.	6700	13	77.00	430	26	0.21	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002

Street History Improvements 1999-2002

21550	Park La.	6800	13	77.00	470	26	0.23	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
21579	Park Row Av.	1800	7	34.00	678	56	0.72	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
21580	Park Row Av.	1900	7	34.00	187	56	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
21591	Parkchester Dr.	11400	11	133.00	935	26	0.46	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
21719	Patonia Av.	5100	5	113.00	900	25	0.43	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
21791	Peak St. (N)	1200	14	15.04	345	40	0.26	Asphalt	1947	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
21792	Peak St. (N)	1300	14	15.03	500	40	0.38	Asphalt	1929	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
21793	Peak St. (N)	1400	14	15.03	383	40	0.29	Asphalt	1929	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
21794	Peak St. (N)	1500	14	15.03	370	40	0.28	Asphalt	1929	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
21798	Peak St. (N)	1900	2	8.00	350	36	0.24	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
21799	Peak St. (N)	2000	2	8.00	162	28	0.09	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
21801	Peak St. (N)	2200	2	8.00	398	24	0.18	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
21861	Peavy Rd.	300	9	129.00	515	40	0.39	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
21874	Peavy Rd.	1600	9	124.00	400	40	0.30	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
21875	Peavy Rd.	1700	9	124.00	500	40	0.38	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
21876	Peavy Rd.	1800	9	124.00	731	40	0.55	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
21877	Peavy Rd.	1900	9	124.00	950	40	0.72	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
21878	Peavy Rd.	2000	9	124.00	715	40	0.54	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
21907	Pebblestone Dr.	7500	11	131.03	315	36	0.21	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
21908	Pebblestone Dr.	7600	11	131.03	315	36	0.21	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
21935	Pemberton Hill Rd.	300	5	93.03	297	36	0.20	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
21936	Pemberton Hill Rd.	400	5	93.03	515	28	0.27	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
21997	Pennsylvania Av.	3400	7	28.00	300	44	0.25	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
32849	Peppermill La.	4200	12	317.02	736	26	0.36	Asphalt	1981	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
22086	Pershing St.	5100	14	9.00	349	26	0.17	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
22087	Pershing St.	5200	14	9.00	374	26	0.18	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
36727	Pheasant Park	5300	3	165.01	674	33	0.42	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
22156	Piedmont Dr.	7000	4	91.01	347	40	0.26	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
22157	Piedmont Dr.	7100	4	91.01	347	40	0.26	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
22158	Piedmont Dr.	7200	4	91.01	853	40	0.65	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
22159	Piedmont Dr.	7300	4	91.01	623	40	0.47	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
22160	Piedmont Dr.	7400	4	91.01	646	40	0.49	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
22161	Piedmont Dr.	7500	4	91.01	735	40	0.56	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
22162	Piedmont Dr.	7600	4	91.01	925	40	0.70	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
22163	Piedmont Dr.	7700	4	91.01	472	40	0.36	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
36842	Pilgrim Rest Dr.	2500	8	109.00	722	26	0.36	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
22222	Pinecrest Dr.	10200	9	124.00	500	26	0.25	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
22264	Plano Pkwy.	8800	10	130.07	936	26	0.46	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
22360	Pleasant Hills Dr.	700	8	118.00	645	26	0.32	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
22361	Pleasant Hills Dr.	800	8	118.00	700	26	0.34	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
22362	Pleasant Hills Dr.	900	8	118.00	700	26	0.34	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
36581	Pleasant Mound	7600	4	91.01	632	26	0.31	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
22380	Pleasant Woods Dr. (S)	100	8	117.00	830	26	0.41	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
22381	Pleasant Woods Dr. (S)	200	8	117.00	444	26	0.22	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
22566	Poplar St.	1600	7	40.00	635	30	0.36	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
22567	Poplar St.	1700	7	40.00	525	30	0.30	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
36796	Port Blvd.	4000	8	167.02	559	44	0.47	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36797	Port Blvd.	4100	8	167.02	559	44	0.47	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36798	Port Blvd.	4200	8	167.02	561	44	0.47	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
22583	Post Dr.	9700	14	94.01	366	26	0.18	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
22720	Preston Rd.	8500	13	75.02	476	66	0.60	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22721	Preston Rd.	8600	13	75.02	521	66	0.65	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22722	Preston Rd.	8700	13	75.02	381	66	0.48	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22723	Preston Rd.	8800	13	75.02	425	66	0.53	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22724	Preston Rd.	8900	13	75.02	529	66	0.66	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22725	Preston Rd.	9000	13	75.02	479	66	0.60	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22726	Preston Rd.	9100	13	75.02	430	66	0.54	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22727	Preston Rd.	9200	13	75.02	428	66	0.54	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000

Street History Improvements 1999-2002

22728	Preston Rd.	9300	13	75.02	416	66	0.52	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22729	Preston Rd.	9400	13	75.02	431	66	0.54	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22730	Preston Rd.	9500	13	75.02	370	66	0.46	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22731	Preston Rd.	9600	13	75.02	300	66	0.38	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22732	Preston Rd.	9700	13	76.03	402	66	0.50	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22733	Preston Rd.	9800	13	76.03	430	66	0.54	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22734	Preston Rd.	9900	13	76.03	368	66	0.46	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22735	Preston Rd.	10000	13	76.03	365	66	0.46	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22736	Preston Rd.	10100	13	76.03	361	66	0.45	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22737	Preston Rd.	10200	13	76.03	465	66	0.58	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22738	Preston Rd.	10300	13	76.03	265	66	0.33	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22739	Preston Rd.	10400	13	76.03	459	66	0.57	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22740	Preston Rd.	10500	13	76.03	519	66	0.65	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22741	Preston Rd.	10600	13	76.03	888	66	1.11	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22742	Preston Rd.	10700	13	76.03	853	66	1.07	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22743	Preston Rd.	10800	13	134.02	920	60	1.05	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22744	Preston Rd.	10900	13	134.02	447	60	0.51	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22745	Preston Rd.	11000	13	134.02	446	60	0.51	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22746	Preston Rd.	11100	13	134.02	445	60	0.51	Asphalt		2001	2001	2000 County	Resurfacing	Other Project	2000 County	2000
22814	Preston View Blvd.	5700	11	136.15	456	30	0.26	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
22815	Preston View Blvd.	5800	11	136.15	457	30	0.26	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
22816	Preston View Blvd.	5900	11	136.15	457	30	0.26	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
22820	Prestoncrest La.	6300	11	132.00	449	26	0.22	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
22821	Prestoncrest La.	6400	11	132.00	623	26	0.31	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
22845	Prichard La.	2100	4	91.01	610	36	0.42	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
22846	Prichard La.	2200	4	91.01	575	36	0.39	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
22847	Prichard La.	2300	4	91.01	370	36	0.25	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
22848	Prichard La.	2400	4	91.01	362	36	0.25	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
22849	Prichard La.	2500	4	91.01	531	36	0.36	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
22850	Prichard La.	2600	4	91.01	780	36	0.53	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
22851	Prichard La.	2700	4	91.01	430	36	0.29	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
22852	Prichard La.	2800	4	91.01	365	36	0.25	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
22853	Prichard La.	2900	4	91.01	1,203	36	0.82	Concrete		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
22871	Profit Dr.	900	6	100.00	1,160	30	0.66	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
22872	Profit Dr.	1000	6	100.00	832	30	0.47	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
22902	Province La.	2400	9	125.00	630	26	0.31	Asphalt		1999	1999	DWU	Resurfacing	Other Project	DWU	1999
22903	Province La.	2500	9	125.00	600	26	0.30	Asphalt		1999	1999	DWU	Resurfacing	Other Project	DWU	1999
22904	Province La.	2600	9	125.00	727	26	0.36	Asphalt		1999	1999	DWU	Resurfacing	Other Project	DWU	1999
22905	Province La.	2700	9	125.00	460	26	0.23	Asphalt		1999	1999	DWU	Resurfacing	Other Project	DWU	1999
22906	Province La.	2800	9	125.00	495	26	0.24	Asphalt		1999	1999	DWU	Resurfacing	Other Project	DWU	1999
22983	Quail Run	11000	10	130.06	783	26	0.39	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
22984	Quail Run	11100	10	130.06	868	26	0.43	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
22985	Quail Run	11200	10	130.06	617	36	0.42	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
22986	Quail Run	11300	10	130.06	1,159	26	0.57	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
23038	Quinn St.	9000	5	92.02	893	26	0.44	Concrete	2000	2000	Construction	Construction	Construction	Construction	2000	
36588	Radcliff Dr.	7000	4	122.02	481	36	0.33	Concrete	1999	1999	Construction	Construction	Construction	Construction	1999	
36647	Radcliff Dr.	7100	4	122.02	1,240	36	0.85	Concrete	2000	2000	Construction	Construction	Construction	Construction	2000	
23070	Raeford Dr.	9100	10	78.12	956	26	0.47	Asphalt	1971	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
23071	Raeford Dr.	9200	10	78.12	750	26	0.37	Asphalt	1971	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
23072	Raeford Dr.	9300	10	78.12	646	26	0.32	Asphalt	1971	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
23107	Ramona Av.	4300	4	59.01	410	36	0.28	Concrete	2000	2000	Construction	Construction	Construction	Construction	2000	
23108	Ramona Av.	4400	4	59.01	390	36	0.27	Concrete	2000	2000	Construction	Construction	Construction	Construction	2000	
23109	Ramona Av.	4500	4	59.01	407	36	0.28	Concrete	2000	2000	Construction	Construction	Construction	Construction	2000	
23110	Ramona Av.	4600	4	59.01	545	36	0.37	Concrete	2000	2000	Construction	Construction	Construction	Construction	2000	
23111	Ramona Av.	4700	4	59.01	327	36	0.22	Concrete	2000	2000	Construction	Construction	Construction	Construction	2000	
23113	Ramona Av.	4900	4	59.01	475	36	0.32	Concrete	2000	2000	Construction	Construction	Construction	Construction	2000	
23115	Ramsey Av.	1400	6	54.00	360	22	0.15	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
23116	Ramsey Av.	1500	6	54.00	343	22	0.14	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002

Street History Improvements 1999-2002

23117	Ramsey Av.	1600	6	54.00	580	22	0.24	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
36800	Raven Row	5300	3	165.01	646	33	0.40	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
23187	Ravenscroft Dr.	10500	11	131.02	555	26	0.27	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
23188	Ravenscroft Dr.	10600	11	131.02	275	26	0.14	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
23213	Ravinia Dr. (S)	500	1	45.00	473	26	0.23	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
23214	Ravinia Dr. (S)	600	1	45.00	401	26	0.20	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
23215	Ravinia Dr. (S)	700	1	45.00	210	26	0.10	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
23216	Ravinia Dr. (S)	800	1	45.00	465	26	0.23	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
23217	Ravinia Dr. (S)	900	1	45.00	864	26	0.43	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
23218	Ravinia Dr. (S)	1000	1	45.00	303	26	0.15	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
23241	Rawlins St.	3600	14	6.04	426	42	0.34	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
23242	Rawlins St.	3700	14	6.04	412	42	0.33	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
23288	Realoaks Dr.	300	5	116.02	350	26	0.17	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
34172	Realoaks Dr.	400	8	116.02	220	26	0.11	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
23383	Redman Cir.	2000	7	25.00	380	26	0.19	Asphalt		2000	2000	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
23399	Redwood Cir.	1300	9	81.00	465	26	0.23	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
34994	Regal Hill Cir.	15600	12	136.07	820	26	0.40	Asphalt	1966	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
23695	Ridgewick Dr.	7500	8	116.01	670	26	0.33	Asphalt	1964	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
23740	Riverbrook Dr.	7500	11	131.03	290	36	0.20	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
23741	Riverbrook Dr.	7600	11	131.03	290	36	0.20	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
33662	Riverside Rd.	4200	8	167.01	1,450	22	0.60	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
23745	Riverside Rd.	4300	8	169.01	565	33	0.35	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
23746	Riverside Rd.	4400	8	169.01	530	18	0.18	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
35972	Robin Song	9600	10	78.11	250	36	0.17	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
34193	Rocky Top Cir.	6800	12	317.98	625	26	0.31	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
34194	Rocky Top Cir.	6900	12	317.98	510	26	0.25	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
32523	Rocky Top Cir.	7000	12	317.98	715	26	0.35	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
23913	Rockyglen Dr.	2300	7	122.04	1,386	26	0.68	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
23921	Rogue Wy.	11600	9	128.00	737	26	0.36	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
23922	Rogue Wy.	11700	9	128.00	569	26	0.28	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
23931	Rolling Hills La.	13200	11	136.10	556	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
36590	Ron Baker Dr.	2500	4	91.01	751	26	0.37	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
36731	Ronryan Rd.	5100	3	165.01	641	24	0.29	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
24045	Ross Av.	900	2	21.00	212	56	0.22	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	95 Bond	2010	2000
24046	Ross Av.	1000	2	21.00	315	56	0.33	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	95 Bond	2010	2000
24047	Ross Av.	1100	2	21.00	220	56	0.23	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	95 Bond	2010	2000
24048	Ross Av.	1200	2	21.00	200	56	0.21	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	95 Bond	2010	2000
24049	Ross Av.	1300	2	21.00	200	56	0.21	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	95 Bond	2010	2000
24050	Ross Av.	1400	2	21.00	235	56	0.25	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	95 Bond	2010	2000
24051	Ross Av.	1500	2	21.00	235	56	0.25	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	95 Bond	2010	2000
24052	Ross Av.	1600	2	21.00	215	56	0.23	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	95 Bond	2010	2000
24053	Ross Av.	1700	2	21.00	162	56	0.17	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	95 Bond	2010	2000
24054	Ross Av.	1800	2	21.00	166	56	0.18	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	95 Bond	2010	2000
24164	Routh St.	3100	14	18.00	409	36	0.28	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
31050	Royal Highlands Dr.	10100	10	130.08	440	26	0.22	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
31051	Royal Highlands Dr.	10200	10	130.08	715	26	0.35	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
24216	Royal La.	2700	2	96.06	1,400	66	1.75	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
24217	Royal La.	2800	2	96.06	700	66	0.88	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
24218	Royal La.	2900	6	96.06	1,280	66	1.60	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
24219	Royal La.	3000	6	96.06	642	66	0.80	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
24220	Royal La.	3100	6	96.06	1,490	66	1.86	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
24221	Royal La.	3200	13	96.07	790	60	0.90	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
24222	Royal La.	3300	13	96.07	990	60	1.13	Asphalt	1969	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
24223	Royal La.	3400	13	96.07	723	60	0.82	Asphalt	1969	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
24224	Royal La.	3500	13	96.07	970	60	1.10	Asphalt	1969	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
24225	Royal La.	3600	13	96.07	875	60	0.99	Asphalt	1969	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
34564	Royal La.	9900	10	78.11	669	72	0.91	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
24367	Ruskin St.	3700	7	37.00	548	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999

Street History Improvements 1999-2002

24406	Rutledge St.	3200	7	37.00	396	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
24407	Rutledge St.	3300	7	37.00	400	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
24457	Sadler Cir.	5700	2	4.03	1,248	26	0.61	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
36593	Sam Rayburn Trl.	3600	12	216.10	470	30	0.27	Concrete	1999	1999	Construction	Construction	Construction	Construction	1999	1999
36594	Sam Rayburn Trl.	3700	12	216.10	535	30	0.30	Concrete	1999	1999	Construction	Construction	Construction	Construction	1999	1999
24598	San Fernando Wy.	9100	9	81.00	460	26	0.23	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
24599	San Fernando Wy.	9200	9	81.00	780	26	0.38	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
24600	San Fernando Wy.	9300	9	81.00	792	26	0.39	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
24613	San Jacinto St.	900	2	21.00	188	30	0.11	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
24614	San Jacinto St.	1000	2	21.00	188	30	0.11	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
24615	San Jacinto St.	1100	2	21.00	330	30	0.19	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
24616	San Jacinto St.	1200	2	21.00	110	30	0.06	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
24617	San Jacinto St.	1300	2	21.00	216	30	0.12	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
24618	San Jacinto St.	1400	2	21.00	250	30	0.14	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
24619	San Jacinto St.	1500	2	21.00	250	30	0.14	Asphalt	1953	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
24623	San Jacinto St.	1900	2	21.00	205	40	0.16	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
24624	San Jacinto St.	2000	2	21.00	360	40	0.27	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
24635	San Jacinto St.	3300	14	16.00	200	36	0.14	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
24636	San Jacinto St.	3400	14	16.00	200	36	0.14	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
24637	San Jacinto St.	3500	14	16.00	250	36	0.17	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
24638	San Jacinto St.	3600	14	16.00	400	36	0.27	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
24639	San Jacinto St.	3700	14	16.00	200	36	0.14	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
24766	Sandpiper La.	10500	11	131.02	585	26	0.29	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
24767	Sandpiper La.	10600	11	131.02	920	26	0.45	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
35716	Sandy Lake Rd.	2300	6	140.02	1,770	44	1.48	Concrete	1999	1999	Construction	Construction	Construction	Construction	1999	1999
24782	Saner Av. (E)	100	6	56.00	360	40	0.27	Asphalt		2000	2000	2000 Resurfacing Group III	Resurfacing	NRP	NRP	2000
24783	Saner Av. (E)	200	6	56.00	380	40	0.29	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
24784	Saner Av. (E)	300	6	56.00	760	40	0.58	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
24785	Saner Av. (E)	400	6	56.00	380	40	0.29	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
24828	Santa Anna Av.	2000	10	127.00	363	40	0.28	Asphalt	1955	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
24829	Santa Anna Av.	2100	10	127.00	363	40	0.28	Asphalt	1955	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
24830	Santa Anna Av.	2200	10	127.00	363	40	0.28	Asphalt	1955	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
24831	Santa Anna Av.	2300	10	127.00	364	40	0.28	Asphalt	1955	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
24832	Santa Anna Av.	2400	10	127.00	364	40	0.28	Asphalt	1955	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
24833	Santa Anna Av.	2500	10	127.00	363	40	0.28	Asphalt	1955	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
24834	Santa Anna Av.	2600	10	127.00	363	40	0.28	Asphalt	1955	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
24835	Santa Anna Av.	2700	10	127.00	364	40	0.28	Asphalt	1955	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
24836	Santa Anna Av.	2800	10	127.00	364	40	0.28	Asphalt	1955	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
36697	Santa Elena Plz.	1400	3	107.02	275	36	0.19	Concrete	2001	2001	Construction	Construction	Construction	Construction	2001	2001
36701	Sarita Ct.	2500	3	108.01	607	36	0.41	Concrete	2001	2001	Construction	Construction	Construction	Construction	2001	2001
36702	Sarita Ct.	2600	3	108.01	556	56	0.59	Concrete	2001	2001	Construction	Construction	Construction	Construction	2001	2001
36703	Sarita Ct.	2700	3	108.01	292	36	0.20	Concrete	2001	2001	Construction	Construction	Construction	Construction	2001	2001
24998	Schroeder Rd.	11800	10	78.04	643	40	0.49	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
24999	Schroeder Rd.	11900	10	78.04	313	40	0.24	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25000	Schroeder Rd.	12000	10	78.04	600	40	0.45	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25001	Schroeder Rd.	12100	10	78.04	435	40	0.33	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25002	Schroeder Rd.	12200	10	78.04	460	40	0.35	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25126	Seagrove Dr.	9100	10	78.12	940	26	0.46	Asphalt	1977	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
25127	Seagrove Dr.	9200	10	78.12	760	26	0.37	Asphalt	1971	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
25128	Seagrove Dr.	9300	10	78.12	630	26	0.31	Asphalt	1971	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
25146	Seaside Dr.	500	8	111.05	498	26	0.25	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
35977	Second Av.	4100	7	37.00	450	44	0.38	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
25194	Second Av.	4200	7	38.00	460	44	0.38	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
25195	Second Av.	4300	7	38.00	310	44	0.26	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
25196	Second Av.	4400	7	38.00	325	44	0.27	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
25197	Second Av.	4500	7	38.00	400	44	0.33	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
25198	Second Av.	4600	7	38.00	470	44	0.39	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
25199	Second Av.	4700	7	39.01	270	44	0.23	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999

Street History Improvements 1999-2002

25200	Second Av.	4800	7	39.01	345	60	0.39	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
25201	Second Av.	4900	7	39.01	460	60	0.52	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
25202	Second Av.	5000	7	39.01	340	60	0.39	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
25203	Second Av.	5100	7	39.01	505	60	0.57	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
25204	Second Av.	5200	7	115.00	200	46	0.17	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
25205	Second Av.	5300	7	115.00	1,770	46	0.77	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
25206	Second Av.	5400	7	115.00	1,770	44	0.74	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
25207	Second Av.	5500	7	115.00	1,770	44	0.74	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
25230	Seevers Av.	1300	6	54.00	423	24	0.19	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25231	Seevers Av.	1400	6	54.00	375	22	0.16	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25232	Seevers Av.	1500	6	54.00	425	22	0.18	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25233	Seevers Av.	1600	6	54.00	330	22	0.14	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25234	Seevers Av.	1700	6	54.00	475	30	0.27	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25235	Seevers Av.	1800	6	54.00	418	30	0.24	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25236	Seevers Av.	1900	6	54.00	430	30	0.24	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25237	Seevers Av.	2000	6	54.00	380	30	0.22	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25238	Seevers Av.	2100	6	54.00	455	30	0.26	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25239	Seevers Av.	2200	6	54.00	395	30	0.22	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
25245	Seevers Av.	2800	6	56.00	648	30	0.37	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
25252	Self Plaza Dr.	12100	10	130.06	514	30	0.29	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
25253	Self Plaza Dr.	12200	10	130.06	514	28	0.27	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
25311	Shadow Bend Dr.	10400	11	131.02	695	26	0.34	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
25342	Shady Hollow La.	3300	6	108.03	725	26	0.36	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
25343	Shady Hollow La.	3400	6	108.03	670	26	0.33	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
25344	Shady Hollow La.	3500	6	108.03	525	26	0.26	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
25345	Shady Hollow La.	3600	6	108.03	160	26	0.08	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
25346	Shady Hollow La.	3700	6	108.03	590	26	0.29	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
25347	Shady Hollow La.	3800	6	108.03	884	26	0.44	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
25348	Shady Hollow La.	3900	6	108.03	426	26	0.21	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
25349	Shady Hollow La.	4000	6	108.03	548	26	0.27	Asphalt		2001	2001	2001 Resurfacing Group II	Resurfacing	General Fund	2010	2001
34220	Shadybank Dr.	16200	12	136.19	725	26	0.36	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
34221	Shadybank Dr.	16300	12	136.19	1,020	26	0.50	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
34222	Shadybank Dr.	16400	12	136.19	386	36	0.26	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
34223	Shadybank Dr.	16500	12	136.19	419	36	0.29	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
25368	Shadycliff Dr.	6100	11	136.08	565	26	0.28	Asphalt	1962	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
25369	Shadycliff Dr.	6200	11	136.08	671	26	0.33	Asphalt	1961	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
25822	Skillman St.	5900	13	78.17	1,185	60	1.35	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
25823	Skillman St.	6000	13	78.17	874	60	0.99	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
25824	Skillman St.	6100	13	78.17	400	60	0.45	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
25825	Skillman St.	6200	13	78.16	333	60	0.38	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
25826	Skillman St.	6300	13	78.16	333	60	0.38	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
25827	Skillman St.	6400	13	78.16	750	60	0.85	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
25918	Snow White Dr.	11600	13	96.09	180	26	0.09	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
25919	Snow White Dr.	11700	13	96.09	909	26	0.45	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
25920	Snow White Dr.	11800	13	96.08	524	26	0.26	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
25921	Snow White Dr.	11900	13	96.08	380	26	0.19	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
25922	Snow White Dr.	12000	13	96.08	330	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
25923	Snow White Dr.	12100	13	96.08	307	26	0.15	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
25924	Snow White Dr.	12200	13	96.08	762	26	0.38	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
25940	Solta Dr.	10400	9	129.00	842	26	0.41	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
25941	Solta Dr.	10500	9	129.00	1,024	26	0.50	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
26050	South Shore Dr.	100	6	54.00	493	22	0.21	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
26051	South Shore Dr.	200	6	54.00	695	22	0.29	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
26037	Southpoint Dr.	6200	12	136.19	274	36	0.19	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
26038	Southpoint Dr.	6300	12	136.19	556	36	0.38	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
26039	Southpoint Dr.	6400	12	136.19	478	36	0.33	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
26126	Sperry St.	3100	9	80.00	470	26	0.23	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
26127	Sperry St.	3200	9	80.00	500	26	0.25	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000

Street History Improvements 1999-2002

26128	Sperry St.	3300	9	80.00	700	26	0.34	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
26129	Sperry St.	3400	9	80.00	359	26	0.18	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
26130	Sperry St.	3500	9	80.00	351	26	0.17	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
26131	Sperry St.	3600	9	80.00	383	26	0.19	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
26132	Sperry St.	3700	9	80.00	334	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
26133	Sperry St.	3800	9	80.00	334	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
26134	Sperry St.	3900	9	80.00	300	26	0.15	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
26135	Sperry St.	4000	9	80.00	550	26	0.27	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
26136	Sperry St.	4100	9	80.00	673	26	0.33	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
26189	Spring Grove Av.	13200	11	136.10	345	26	0.17	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
26190	Spring Grove Av.	13300	11	136.10	470	26	0.23	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
35847	Spring Valley Rd. (N)	6500	11	136.08	370	26	0.18	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
35721	Spring Valley Rd. (N)	6600	11	136.08	465	26	0.23	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
26265	Spruce Valley La.	3200	6	108.03	829	26	0.41	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
26266	Spruce Valley La.	3300	6	108.03	323	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
26267	Spruce Valley La.	3400	6	108.03	564	26	0.28	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
26361	St Francis Av.	1700	9	81.00	615	26	0.30	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
26362	St Francis Av.	1800	7	122.03	400	26	0.20	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36851	St Luke La.	2500	8	109.00	780	26	0.38	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
26293	St. Augustine Dr. (N)	1100	5	118.00	569	40	0.43	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
26294	St. Augustine Dr. (N)	1200	5	118.00	490	40	0.37	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
26548	State St.	2800	14	17.02	355	36	0.24	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
26550	State St.	3000	14	17.02	417	34	0.27	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
26551	State St.	3100	14	17.02	445	34	0.29	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
26552	State St.	3200	14	17.02	264	34	0.17	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
26564	Stefani Dr.	6000	13	77.00	610	26	0.30	Asphalt		2001	2001	2001 City Wide	Resurfacing	General Fund	City Wide	2001
26565	Stefani Dr.	6100	13	77.00	663	26	0.33	Asphalt		2001	2001	2001 City Wide	Resurfacing	General Fund	City Wide	2001
26566	Stefani Dr.	6200	13	77.00	740	26	0.36	Asphalt		2001	2001	2001 City Wide	Resurfacing	General Fund	City Wide	2001
26567	Stefani Dr.	6300	13	77.00	630	26	0.31	Asphalt		2001	2001	2001 City Wide	Resurfacing	General Fund	City Wide	2001
36597	Steinhagen La.	18300	12	216.10	250	30	0.14	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
33363	Steppington Dr.	10500	11	131.03	501	36	0.34	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
33364	Steppington Dr.	10600	11	131.03	501	36	0.34	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
33365	Steppington Dr.	10700	11	131.03	501	36	0.34	Asphalt	1982	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
33366	Steppington Dr.	10800	11	131.03	501	36	0.34	Asphalt	1973	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
26633	Stillwater Dr.	8500	10	78.05	754	26	0.37	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
26649	Stone Canyon Rd.	10400	11	131.03	300	36	0.20	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
26650	Stone Canyon Rd.	10500	11	131.03	1,300	36	0.89	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
26651	Stone Canyon Rd.	10600	11	131.03	524	36	0.36	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
26652	Stone Canyon Rd.	10700	11	131.03	285	36	0.19	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
26653	Stone Canyon Rd.	10800	11	131.03	1,237	36	0.84	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
26654	Stone Canyon Rd.	10900	11	131.03	802	36	0.55	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
26669	Stonehaven Dr.	6400	11	136.08	309	26	0.15	Asphalt	1970	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
34245	Stonehurst St.	8300	5	92.01	145	33	0.09	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
26673	Stonehurst St.	8400	5	92.01	270	33	0.17	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
26674	Stonehurst St.	8600	5	92.01	671	26	0.33	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
26675	Stonehurst St.	8700	5	92.01	500	26	0.25	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
26690	Stoneport Dr.	200	5	93.04	520	36	0.35	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
26691	Stoneport Dr.	300	5	93.04	1,240	26	0.61	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
31080	Summer Glen La.	9000	10	78.12	1,005	26	0.49	Asphalt	1977	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
31081	Summer Glen La.	9100	10	78.12	945	26	0.47	Asphalt	1975	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
26861	Sunburst Dr.	500	8	118.00	737	26	0.36	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
26862	Sunburst Dr.	600	8	118.00	568	26	0.28	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
26863	Sunburst Dr.	700	8	118.00	686	26	0.34	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
26947	Superior St.	1100	1	53.00	690	26	0.34	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
26969	Susan St.	4900	3	107.01	312	26	0.15	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
26971	Sussex Av.	1900	6	55.00	363	26	0.18	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
27076	Sylvan Av.	1300	3	44.00	605	60	0.69	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
27077	Sylvan Av.	1400	3	44.00	673	60	0.76	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999

Street History Improvements 1999-2002

27078	Sylvan Av.	1500	3	44.00	656	60	0.75	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
27079	Sylvan Av.	1600	3	44.00	1,092	60	1.24	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
27080	Sylvan Av.	1700	3	44.00	350	60	0.40	Concrete		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
27098	Sylvan Av.	3500	6	101.01	947	28	0.50	Asphalt	1968	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
27099	Sylvan Av.	3600	6	101.01	756	28	0.40	Asphalt	1968	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
27100	Sylvan Av.	3700	6	100.00	656	28	0.35	Asphalt	1969	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
27101	Sylvan Av.	3800	6	100.00	656	28	0.35	Asphalt	1969	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
27113	Sylvia Dr.	10200	9	124.00	550	26	0.27	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
27114	Sylvia Dr.	10300	9	124.00	710	26	0.35	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	General Fund	2010	2000
27129	Tackett St.	8400	5	92.01	785	26	0.39	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
27191	Tangleridge La.	13400	11	136.08	365	26	0.18	Asphalt	1962	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
27222	Tarryall Dr.	600	4	60.02	620	26	0.31	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
27223	Tarryall Dr.	700	4	60.02	330	26	0.16	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
27224	Tarryall Dr.	800	4	60.02	430	26	0.21	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
27225	Tarryall Dr.	900	4	60.02	450	26	0.22	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
27226	Tarryall Dr.	1000	4	60.02	410	26	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
27304	Tellerson Av.	9800	9	125.00	969	26	0.48	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
27315	Tenino St.	8300	5	92.02	615	26	0.30	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
27316	Tenino St.	8400	5	92.02	675	26	0.33	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
27352	Tenth St. (E)	200	1	48.00	456	30	0.26	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
27353	Tenth St. (E)	300	1	48.00	454	30	0.26	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
27354	Tenth St. (E)	400	1	48.00	463	30	0.26	Asphalt		1999	1999	CDBG	Resurfacing	Other Project	CDBG	1999
27355	Tenth St. (E)	500	1	48.00	596	30	0.34	Asphalt		1999	1999	CDBG	Resurfacing	Other Project	CDBG	1999
27356	Tenth St. (E)	600	1	48.00	417	40	0.32	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
27391	Teresa La.	8300	5	92.02	966	26	0.48	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
35064	Terrace Lawn Cir.	15600	12	136.07	820	26	0.40	Asphalt	1966	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
27514	Thomas Av.	3000	14	17.02	440	34	0.28	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
27515	Thomas Av.	3100	14	17.02	313	34	0.20	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
27516	Thomas Av.	3200	14	17.02	296	34	0.19	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
27549	Throckmorton St.	3800	14	6.04	167	36	0.11	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	95 Bond	2010	2000
27550	Throckmorton St.	3900	14	6.04	305	36	0.21	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	95 Bond	2010	2000
36602	Timberglen Rd.	3600	12	216.10	1,017	44	0.85	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
27844	Topsfield Dr.	6800	10	78.13	630	26	0.31	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
27845	Topsfield Dr.	6900	10	78.13	693	26	0.34	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
36692	Toscano Dr.	2600	3	108.01	452	36	0.31	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
27835	Town North Dr.	6800	9	78.09	766	36	0.52	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
27836	Town North Dr.	6900	9	78.09	878	36	0.60	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
27837	Town North Dr.	7000	9	78.09	975	36	0.66	Asphalt		2001	2001	2000 Resurfacing Group I	Resurfacing	NCE Bond	2010	2000
33379	Townsley Ct.	17200	12	136.18	496	26	0.24	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
27913	Transit St.	8300	5	117.00	315	26	0.16	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
27914	Transit St.	8400	5	117.00	500	26	0.25	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
32954	Trellis Ct.	4300	2	15.02	495	18	0.07	Asphalt		1999	1999	Other Project	Resurfacing	Other Project	Other Project	1999
36856	Trinity Gate Dr.	7700	8	109.00	282	32	0.17	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
36857	Trinity Gate Dr.	7800	8	109.00	602	32	0.36	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
36858	Trinity Gate Dr.	7900	8	109.00	534	32	0.32	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
36689	Tristian Ct.	2500	3	108.01	352	36	0.24	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36690	Tristian Ct.	2600	3	108.01	508	36	0.35	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36691	Tristian Ct.	2700	3	108.01	159	36	0.11	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
28127	Twelfth St. (W)	100	1	50.00	472	60	0.54	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
28128	Twelfth St. (W)	200	1	50.00	550	60	0.63	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
28129	Twelfth St. (W)	300	1	50.00	560	60	0.64	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
28130	Twelfth St. (W)	400	1	50.00	590	60	0.67	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
28131	Twelfth St. (W)	500	1	50.00	600	60	0.68	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
28132	Twelfth St. (W)	600	1	50.00	548	60	0.62	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
28133	Twelfth St. (W)	700	1	50.00	555	60	0.63	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
28134	Twelfth St. (W)	800	1	50.00	560	60	0.64	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
28135	Twelfth St. (W)	900	1	51.00	550	60	0.63	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
28233	Uarda Dr.	700	8	118.00	607	26	0.15	Asphalt	1970	2002	2002	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001

Street History Improvements 1999-2002

36859	Unity Wy.	2400	8	109.00	429	40	0.33	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
28275	University Blvd. (W)	5300	14	71.01	689	30	0.39	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
28276	University Blvd. (W)	5400	14	71.01	789	30	0.45	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
28277	University Blvd. (W)	5500	14	71.01	722	30	0.41	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
36605	Urban Av.	4900	4	122.02	561	34	0.36	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
36646	Urban Av.	5000	4	122.02	665	34	0.43	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
28324	Utica Dr.	2100	4	91.01	650	26	0.32	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
28325	Utica Dr.	2200	4	91.01	579	26	0.29	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
28326	Utica Dr.	2300	4	91.01	400	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
28327	Utica Dr.	2400	4	91.01	461	26	0.23	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
28328	Utica Dr.	2500	4	91.01	408	26	0.20	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	General Fund	2010	1999
33390	Valleydale Dr.	11500	11	131.01	755	26	0.37	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
33391	Valleydale Dr.	11600	11	131.01	690	26	0.34	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
28363	Valleydale Dr.	11700	11	131.01	753	26	0.37	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
28430	Van Ness Pl.	3800	14	94.01	122	40	0.09	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
28456	Vanderbilt Av.	6100	14	2.01	1,040	28	0.55	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
28457	Vanderbilt Av.	6200	14	2.01	640	30	0.36	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
28458	Vanderbilt Av.	6300	14	2.01	938	30	0.53	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
28524	Vermont Av.	700	6	54.00	367	35	0.24	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
28525	Vermont Av.	800	6	54.00	365	35	0.24	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
35073	Vermont Av.	900	6	54.00	200	35	0.13	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
28532	Vernon Av. (N)	100	1	47.00	430	30	0.24	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
28544	Vernon Av. (S)	600	1	50.00	332	30	0.19	Asphalt	1963	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
28545	Vernon Av. (S)	700	1	50.00	340	30	0.19	Asphalt	1963	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
28546	Vernon Av. (S)	800	1	50.00	505	30	0.29	Asphalt	1963	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
28547	Vernon Av. (S)	900	1	50.00	293	30	0.17	Asphalt	1963	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
28548	Vernon Av. (S)	1000	1	50.00	265	26	0.13	Asphalt	1963	2001	2001	2001 Resurfacing Group II	Resurfacing	98 Bond	2010	2001
36118	Vicksburg St.	4900	6	100.00	200	36	0.14	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
36789	Victory Av.	2200	2	19.00	268	44	0.22	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36790	Victory Av.	2300	2	19.00	580	44	0.48	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36791	Victory Av.	2400	2	19.00	580	44	0.48	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36792	Victory Av.	2500	2	19.00	594	44	0.50	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
36793	Victory Av.	2600	2	19.00	1,254	44	1.05	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
28635	Viewcrest Dr.	1800	9	124.00	600	26	0.30	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
28636	Viewcrest Dr.	1900	9	124.00	490	26	0.24	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	General Fund	2010	2002
31098	Villa Rd.	6200	12	317.98	180	26	0.09	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
31099	Villa Rd.	6300	12	317.98	410	26	0.20	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
31100	Villa Rd.	6400	12	317.98	651	26	0.32	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
31101	Villa Rd.	6500	12	317.98	463	26	0.23	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
31102	Villa Rd.	6600	12	317.98	623	26	0.31	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
28755	Vista Gate Dr.	8900	10	78.12	478	26	0.24	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
36698	Vista Real Dr.	1400	3	107.02	300	36	0.20	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
31575	Vista Willow Dr.	6900	12	136.19	1,320	26	0.65	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
28749	Vistadale Cir.	10300	10	130.09	146	26	0.07	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
34288	Vistadale Dr.	10200	10	130.09	700	26	0.34	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
34289	Vistadale Dr.	10300	10	130.09	395	26	0.19	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
34290	Vistadale Dr.	10400	10	130.09	680	26	0.33	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
32962	Voss Rd.	18700	12	317.02	620	40	0.47	Asphalt	1981	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
32963	Voss Rd.	18800	12	317.02	715	26	0.35	Asphalt	1981	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
28780	Wabash Cir.	6900	9	80.00	735	26	0.36	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
28789	Waco Av. (E)	1300	6	49.00	740	24	0.34	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
36497	Wanklyn Ct.	3900	8	109.00	175	36	0.12	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
28983	Warm Moon La.	6500	8	167.01	568	26	0.28	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
29029	Washington Av. (N)	2400	14	16.00	259	30	0.15	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
29049	Waterhouse Dr.	3900	8	167.01	435	26	0.21	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
29065	Waterview Rd.	9700	9	129.00	557	26	0.27	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
29066	Waterview Rd.	9800	9	129.00	628	26	0.31	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
35857	Watsonwood St.	400	8	170.02	951	30	0.54	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001

Street History Improvements 1999-2002

35858	Watsonwood St.	500	8	170.02	706	30	0.40	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
29257	Wellcrest Dr.	7300	11	131.02	725	26	0.36	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
29258	Wellcrest Dr.	7400	11	131.02	480	26	0.24	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
29272	Wendelkin St.	3200	7	34.00	230	30	0.13	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
31113	Wendelkin St.	3300	7	34.00	225	30	0.13	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
29273	Wendelkin St.	3400	7	34.00	381	30	0.22	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
29274	Wendelkin St.	3500	7	40.00	440	30	0.25	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
29275	Wendelkin St.	3600	7	40.00	562	30	0.32	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
29276	Wendelkin St.	3700	7	40.00	521	30	0.30	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
29277	Wendelkin St.	3800	7	40.00	350	30	0.20	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
29309	Wes Hodges Rd.	8200	5	92.02	639	26	0.31	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
29315	Westbrook La.	7100	9	79.02	725	26	0.36	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
29316	Westbrook La.	7200	9	79.02	625	26	0.31	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
29412	Westmoreland Rd. (N)	3000	6	105.00	280	64	0.34	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
29413	Westmoreland Rd. (N)	3100	6	105.00	384	64	0.47	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
29414	Westmoreland Rd. (N)	3200	6	105.00	356	64	0.43	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
29415	Westmoreland Rd. (N)	3300	6	105.00	365	64	0.44	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
29416	Westmoreland Rd. (N)	3400	6	105.00	393	64	0.48	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
29417	Westmoreland Rd. (N)	3500	6	105.00	618	64	0.75	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
29418	Westmoreland Rd. (N)	3600	6	105.00	505	64	0.61	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
29419	Westmoreland Rd. (N)	3700	6	105.00	392	64	0.48	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
29420	Westmoreland Rd. (N)	3800	6	105.00	442	64	0.54	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
29421	Westmoreland Rd. (N)	3900	6	105.00	265	64	0.32	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
29422	Westmoreland Rd. (N)	4000	6	105.00	540	64	0.65	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
29423	Westmoreland Rd. (N)	4100	6	105.00	430	64	0.52	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
29517	Westport Av.	800	6	89.00	368	26	0.18	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
29607	Whispering Pines Dr.	7200	12	136.05	575	26	0.28	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
29608	Whispering Pines Dr.	7300	12	136.05	560	26	0.28	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
29609	Whispering Pines Dr.	7400	12	136.05	650	26	0.32	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
36612	White Pine La.	8900	10	130.04	725	30	0.41	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
29621	White Rock Dr.	1200	9	81.00	683	26	0.34	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
29622	White Rock Dr.	1300	9	81.00	560	26	0.28	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
29623	White Rock Dr.	1400	9	81.00	510	26	0.25	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
29624	White Rock Dr.	1500	9	81.00	483	26	0.24	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
36786	Wichita St.	1400	2	19.00	551	56	0.58	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
29717	Wichita St.	1500	2	19.00	551	56	0.58	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
34304	Wickerwood Dr.	6400	12	136.19	440	26	0.22	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
34305	Wickerwood Dr.	6500	12	136.19	675	26	0.33	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
36864	Widgeon Wy.	8400	3	165.10	942	36	0.64	Concrete	2002		2002	Construction	Construction	Construction	Construction	2002
31126	Wind Mill Cir.	6300	12	317.98	807	26	0.40	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
31127	Wind Mill La.	19100	12	317.98	1,250	26	0.62	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
31116	Winding Ridge Dr.	9400	10	130.08	650	26	0.32	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
31117	Winding Ridge Dr.	9500	10	130.08	500	26	0.25	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
31118	Winding Ridge Dr.	9600	10	130.08	300	26	0.15	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
31119	Winding Ridge Dr.	9700	10	130.08	350	26	0.17	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
34313	Winding Ridge Dr.	9800	10	130.08	291	26	0.14	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
34314	Winding Ridge Dr.	9900	10	130.08	200	26	0.10	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	General Fund	2010	1999
32968	Windy Crest Dr.	9000	10	78.10	954	26	0.47	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
34312	Windy Ridge Dr.	6900	12	136.19	1,109	26	0.55	Asphalt		2000	2000	2000 Resurfacing Group I	Resurfacing	98 Bond	2010	2000
30082	Winterwood La.	7100	12	136.07	614	26	0.30	Asphalt	1971	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
30083	Winterwood La.	7200	12	136.07	441	26	0.22	Asphalt	1971	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
30143	Wolfwood La.	8600	5	92.01	1,073	26	0.53	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
30155	Wood Dale Dr.	10600	9	127.00	1,145	26	0.56	Asphalt		1999	1999	1999 Resurfacing Group I	Resurfacing	98 Bond	2010	1999
30194	Woodbine Av.	900	6	49.00	311	18	0.11	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
30195	Woodbine Av.	1000	6	49.00	345	18	0.12	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
30196	Woodbine Av.	1100	6	49.00	364	18	0.12	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
30197	Woodbine Av.	1200	6	49.00	340	18	0.12	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001
30198	Woodbine Av.	1300	6	49.00	450	24	0.20	Concrete	2001		2001	Construction	Construction	Construction	Construction	2001

Street History Improvements 1999-2002

30213	Woodcastle Dr.	8600	5	92.01	655	26	0.32	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
30214	Woodcastle Dr.	8700	5	92.01	938	26	0.46	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
30215	Woodcastle Dr.	8800	5	92.01	444	26	0.22	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
30216	Woodcastle Dr.	8900	5	92.01	323	26	0.16	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
30240	Woodin Blvd. (E)	100	6	54.00	362	36	0.25	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
30241	Woodin Blvd. (E)	200	6	54.00	365	36	0.25	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
30242	Woodin Blvd. (E)	300	6	54.00	740	36	0.50	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
30243	Woodin Blvd. (E)	400	6	54.00	344	36	0.23	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
30244	Woodin Blvd. (E)	500	6	54.00	362	36	0.25	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
30245	Woodin Blvd. (E)	600	6	54.00	334	36	0.23	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
30249	Woodin Blvd. (E)	1000	6	55.00	331	36	0.23	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
30250	Woodin Blvd. (E)	1100	6	55.00	535	36	0.36	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
30251	Woodin Blvd. (E)	1200	6	55.00	736	36	0.50	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	General Fund	2010	2000
30254	Woodin Blvd. (W)	100	6	54.00	526	25	0.25	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
30255	Woodin Blvd. (W)	200	6	54.00	553	25	0.26	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
30334	Woodthrush Dr.	7300	11	131.02	560	26	0.28	Asphalt		2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
30335	Woodthrush Dr.	7400	11	131.02	450	26	0.22	Asphalt	1968	2001	2001	2001 Resurfacing Group I	Resurfacing	98 Bond	2010	2001
30373	Word St.	3500	14	16.00	194	26	0.10	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
30374	Word St.	3600	14	16.00	411	26	0.20	Asphalt		2000	2000	2000 Resurfacing Group II	Resurfacing	98 Bond	2010	2000
30410	Worthington St.	2300	14	17.02	336	30	0.19	Concrete	1999		1999	Construction	Construction	Construction	Construction	1999
30453	Wycliff Av.	1200	6	100.00	560	60	0.64	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
30454	Wycliff Av.	1300	6	100.00	441	60	0.50	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
30455	Wycliff Av.	1400	6	100.00	531	60	0.60	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
30456	Wycliff Av.	1500	6	100.00	399	60	0.45	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
30457	Wycliff Av.	1600	6	100.00	398	60	0.45	Asphalt		2002	2002	2002 Resurfacing Group I	Resurfacing	98 Bond	2010	2002
30488	Wynnewood Dr.	2300	3	62.00	537	26	0.26	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
30489	Wynnewood Dr.	2400	3	62.00	315	26	0.16	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
30490	Wynnewood Dr.	2500	3	62.00	300	26	0.15	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
30491	Wynnewood Dr.	2600	3	62.00	375	26	0.18	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
30492	Wynnewood Dr.	2700	3	62.00	524	26	0.26	Asphalt		1999	1999	1999 Resurfacing Group II	Resurfacing	98 Bond	2010	1999
30579	Young St.	1000	2	31.01	194	60	0.22	Asphalt		2000	2000	DWU	Resurfacing	DWU	DWU	2000
30622	Zang Blvd. (N)	600	1	42.00	444	60	0.50	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
30623	Zang Blvd. (N)	700	1	42.00	574	60	0.65	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
30624	Zang Blvd. (N)	800	1	42.00	553	60	0.63	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
30625	Zang Blvd. (N)	900	1	42.00	310	60	0.35	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000
30626	Zang Blvd. (N)	1000	1	42.00	718	60	0.82	Concrete	2000		2000	Construction	Construction	Construction	Construction	2000

**PRELIMINARY 2003 LIST OF CONSTRUCTION, RECONSTRUCTION and RESURFACING IMPROVEMENTS - SEE WORK PLANS FOR MORE INFORMATION**

4292	Cason St.	4700	7	39.01	396.00	10.00	0.08	Concrete	2003	2003	Construction	Construction	Construction	Construction	2003
4293	Cason St.	4800	7	39.01	396.00	10.00	0.08	Concrete	2003	2003	Construction	Construction	Construction	Construction	2003
4294	Cason St.	4900	7	39.01	396.00	10.00	0.08	Concrete	2003	2003	Construction	Construction	Construction	Construction	2003
4295	Cason St.	5000	7	39.01	396.00	10.00	0.08	Concrete	2003	2003	Construction	Construction	Construction	Construction	2003
176	Adams Av. (S)	800	1	50.00	495.00	30.00	0.11	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund		
177	Adams Av. (S)	900	1	50.00	350.00	30.00	0.20	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
178	Adams Av. (S)	1000	1	50.00	496.00	30.00	0.28	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
681	Amity La.	1300	5	119.00	1098.00	26.00	0.54	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
682	Amity La.	1400	5	119.00	363.00	26.00	0.18	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
683	Amity La.	1500	5	119.00	744.00	26.00	0.37	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
684	Amity La.	1600	5	119.00	350.00	36.00	0.24	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
685	Amity La.	1700	5	119.00	645.00	26.00	0.32	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
1535	Barnes Av.	11400	9	128.00	681.00	26.00	0.34	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
1768	Beckley Av. (S)	1300	6	54.00	315.00	40.00	0.24	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
1769	Beckley Av. (S)	1400	6	54.00	450.00	40.00	0.34	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
1770	Beckley Av. (S)	1500	6	54.00	297.00	40.00	0.23	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
1771	Beckley Av. (S)	1600	6	54.00	452.00	40.00	0.34	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
1772	Beckley Av. (S)	1700	6	54.00	361.00	40.00	0.27	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
2521	Bolivar Dr.	3700	14	94.01	899.00	26.00	0.44	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
3046	Brockbank Ct.	10700	6	97.01	163.00	26.00	0.08	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
3261	Brown St.	4100	14	5.00	381.00	30.00	0.22	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
3262	Brown St.	4200	14	5.00	386.00	30.00	0.22	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
3263	Brown St.	4300	14	5.00	690.00	26.00	0.34	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
3380	Bryan St.	3000	14	16.00	490.00	36.00	0.33	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
3381	Bryan St.	3100	14	16.00	300.00	30.00	0.17	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
3382	Bryan St.	3200	14	16.00	325.00	30.00	0.18	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
4471	Cedar Springs Rd.	3400	14	5.00	689.00	44.00	0.57	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
4472	Cedar Springs Rd.	3500	14	5.00	425.00	44.00	0.35	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
4473	Cedar Springs Rd.	3600	14	5.00	430.00	44.00	0.36	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
4474	Cedar Springs Rd.	3700	14	5.00	324.00	55.00	0.34	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
4646	Chalmers St.	1400	1	53.00	620.00	22.00	0.13	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
5603	Colorado Blvd. (W)	2000	3	44.00	606.00	34.00	0.39	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
5604	Colorado Blvd. (W)	2100	3	68.00	715.00	44.00	0.60	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
5678	Commerce St.	3700	2	31.02	270.00	40.00	0.20	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
5679	Commerce St.	3800	2	31.02	270.00	40.00	0.20	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
5680	Commerce St.	3900	2	31.02	240.00	40.00	0.18	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
5770	Congress Av.	4300	14	5.00	605.00	30.00	0.34	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
6022	Cortez Dr.	3500	2	98.02	944.00	26.00	0.46	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
6023	Cortez Dr.	3600	2	98.02	676.00	26.00	0.33	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
6024	Cortez Dr.	3700	14	94.01	911.00	26.00	0.45	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
6025	Cortez Dr.	3800	14	94.01	1258.00	26.00	0.62	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
6026	Cortez Dr.	3900	13	94.02	1201.00	26.00	0.59	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
8283	Elizabeth St.	3000	14	7.01	403.00	30.00	0.23	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
8284	Elizabeth St.	3100	14	7.01	412.00	30.00	0.23	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
8718	Eustis Av.	8500	9	81.00	946.00	26.00	0.47	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
10295	Gardenside Dr.	1400	5	119.00	600.00	26.00	0.30	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
10296	Gardenside Dr.	1500	5	119.00	600.00	26.00	0.30	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
10297	Gardenside Dr.	1600	5	119.00	315.00	26.00	0.16	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
11095	Grant St.	1300	6	49.00	777.00	20.00	0.29	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
12134	Harwood St. (N)	100	2	31.01	230.00	50.00	0.22	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
12135	Harwood St. (N)	200	2	31.01	222.00	50.00	0.21	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
12136	Harwood St. (N)	300	2	21.00	244.00	44.00	0.20	Asphalt			2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003

Street History Improvements 1999-2002

14713	Kiest Blvd. (W)	2800	3	108.02	600.00	60.00	0.68	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
14714	Kiest Blvd. (W)	2900	3	108.02	255.00	60.00	0.29	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
14715	Kiest Blvd. (W)	3000	3	108.02	500.00	60.00	0.57	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
15039	Knight St.	3500	14	6.04	350.00	30.00	0.20	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
15040	Knight St.	3600	14	6.04	399.00	30.00	0.23	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
15041	Knight St.	3700	14	6.04	392.00	30.00	0.11	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
17305	Mahon St.	2400	14	18.00	349.00	30.00	0.20	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
17306	Mahon St.	2500	14	18.00	385.00	30.00	0.22	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
	Marsh Serv. La. W	9400	14	98.02	690.00	42.00	0.55	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
18727	Mercedes Av.	5700	14	2.02	629.00	26.00	0.31	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
18728	Mercedes Av.	5800	14	2.02	658.00	26.00	0.32	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
19868	Mountain Lake Rd.	2500	3	108.02	740.00	26.00	0.36	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
19869	Mountain Lake Rd.	2600	3	108.02	875.00	26.00	0.43	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
22039	Pentagon Pkwy. (W)	1400	6	61.00	750.00	40.00	0.57	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
22040	Pentagon Pkwy. (W)	1500	6	61.00	1300.00	40.00	0.98	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
22041	Pentagon Pkwy. (W)	1600	6	61.00	650.00	40.00	0.49	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
22641	Prairie Creek Rd. (N)	3000	4	121.00	250.00	60.00	0.28	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
22642	Prairie Creek Rd. (N)	3100	4	121.00	250.00	60.00	0.28	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
22643	Prairie Creek Rd. (N)	3200	4	121.00	250.00	60.00	0.28	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
22644	Prairie Creek Rd. (N)	3300	4	121.00	250.00	60.00	0.28	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
22645	Prairie Creek Rd. (N)	3400	4	121.00	250.00	60.00	0.28	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
22646	Prairie Creek Rd. (N)	3500	4	121.00	250.00	60.00	0.28	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
22647	Prairie Creek Rd. (N)	3600	4	121.00	250.00	60.00	0.28	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
23535	Reynolds Av.	2900	2	25.00	397.00	24.00	0.18	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
23536	Reynolds Av.	3000	2	25.00	375.00	24.00	0.17	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
23537	Reynolds Av.	3100	2	25.00	355.00	24.00	0.16	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
23538	Reynolds Av.	3200	2	25.00	611.00	24.00	0.28	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
23539	Reynolds Av.	3300	2	25.00	373.00	24.00	0.17	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
24165	Routh St.	3500	14	5.00	471.00	30.00	0.27	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
24166	Routh St.	3600	14	5.00	442.00	30.00	0.25	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
24167	Routh St.	3700	14	5.00	283.00	30.00	0.16	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
24844	Santa Clara Dr.	8100	9	81.00	1155.00	26.00	0.57	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
24845	Santa Clara Dr.	8200	9	81.00	795.00	26.00	0.39	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
24846	Santa Clara Dr.	8300	9	81.00	1030.00	26.00	0.51	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
24847	Santa Clara Dr.	8400	9	81.00	876.00	26.00	0.43	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
24848	Santa Clara Dr.	8500	9	81.00	907.00	26.00	0.45	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
25788	Skiles St.	1300	14	22.01	500.00	32.00	0.30	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
27649	Timberline Dr.	9600	2	72.01	875.00	26.00	0.43	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
27650	Timberline Dr.	9700	2	72.01	630.00	26.00	0.31	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
27651	Timberline Dr.	9800	2	72.01	315.00	26.00	0.16	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003
27652	Timberline Dr.	9900	2	72.01	312.00	26.00	0.15	Asphalt	2003 Resurfacing, Restoration & Rehabilitation	Resurfacing	General Fund	2010	2003